



Altium design & DXF: Notice the slight RF trace notch into the antenna structure (blue arrows below)



EVM: Notch is missing on actual fabricated mmWave EVM boards.

