


HDMI_Female




TEXAS INSTRUMENTS

SCHEMATIC TITLE
SN65TMD5361 EVM

PAGE TITLE
High Speed RX/TX
<Page Title 2>


ENGINEER <OrgAddr1>	DATE <Date>
LAYOUT <OrgAddr2>	DATE <Date1>
RELEASED <OrgAddr3>	DATE <Date2>

Size A	Document Number <Doc>	Rev A	Sheet 1 of 7
-----------	--------------------------	----------	-----------------



PAGE TITLE			
<PAGE TITLE>			
SIZE	DOCUMENT NUMBER	REV	PAGE
A	<Document Number>	<REV>	2 of 7

HDMI_Female



TEXAS INSTRUMENTS

PAGE TITLE

<PAGE TITLE>

SIZE

A

DOCUMENT NUMBER

<Document Number>

REV

<REV>


PAGE

of 7

R16: 4.7k for TMD361 and 0 for TMD351


This should 5V and not 3p3V

I2C_SEL for TMD351 is EQ




TEXAS INSTRUMENTS

PAGE TITLE Control			
SIZE A	DOCUMENT NUMBER <Document Number>	REV A	PAGE 5 of 7



Remove R34 and install JUMP7 to provide 5V +/- 10%



TEXAS INSTRUMENTS

PAGE TITLE 5V Power			
SIZE A	DOCUMENT NUMBER 6502334	REV A	PAGE 6 of 7

