

# MAX 232N



MAX232IN

WORK AT ~ 45 KHz

WORK AT ~ 400 KHz

WORKING PROPERLY

NOT WORKING  
(OVERHEATING)

Purchased a few years ago

Purchased in 2022 in order to test their behaviour after the previously encountered issues (overheating, general malfunctioning)

Purchased in 2020 (17AJ46M) and in 2022 (21AJ46M)