



Measurement Block Diagram



Device recognition is OK
USB DM become High.



Device recognition is failed.

At some boards, it is rarely happened recognition fail.

USB DM does not become High, device recognition is failed.