

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20190523001 Datasheet for TXB0304 Information Only

Date: September 04, 2019

Dear TI Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN team (PCN www admin team@list.ti.com).

Sincerely,

PCN Team SC Business Services

Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICETXB0304RUTR
TXB0304RUTR

CUSTOMER PART NUMBER36020404
36020404/TXB0304RUTR

Technical details of this Product Change follow on the next page(s).

PCN Number:		20190523001 P		CN Date:	Sept. 4, 2019				
Title: Datasheet for TXB0304									
Custom	er Contact:	PCN Manager			Dept	:	Quality Services		
Change Type:									
			Design		☐ Wafer Bump Site				
			Data Sheet	Sheet Wafer Bump Materia		Bump Material			
			Part number change			Wafer Bump Process			
			Test Site			Vafer Fab Site			
☐ Packing/Shipping/Labeling ☐ 1			Test Process				afer Fab Materials		
						Wafer Fab Process			
Notification Details									
Description of Change:									
Texas Instruments Incorporated is announcing an information only notification.									
The product datasheet(s) is being updated as summarized below.									
The following change history provides further details.									
Bia T									
	EXAS NSTRUMENTS						TXB0304		
- 11	NSTRUMENTS			5	SCES831G	-SEPTEM	MBER 2011-REVISED MAY 2019		
Changes from Revision F (May 2016) to Revision G Page									
Changed text in Power Supply Recomendations section.									
The datasheet number will be changing.									
Device Family			Change From:		С	Change To:			
			SCES831F	CES831F		SCES831G			
TXB0304			30230311	.20011					
These ch	nanges may be	reviewed at the	datasheet li	nks provided.					
http://www.ti.com/product/TXB0304									
Reason for Change:									
To accurately reflect device characteristics.									
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):									
_							ere are no changes		
to the actual device.									
Changes to product identification resulting from this PCN:									
None.									
Product Affected:									
_	WP0204BCVB		TVDNO204DLITD						
	XB0304RSVR TXB0304RUTR		K	TXBN0304R	BN0304RSVR TXBI		TXBN0304RUTR		

For questions regarding this notice, e-mails can be sent to the contacts shown below or your local Field Sales Representative. $\frac{1}{2} \left(\frac{1}{2} \right) = \frac{1}{2} \left(\frac{1}{2} \right) \left(\frac{1}{$

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
WW PCN Team	PCN www admin team@list.ti.com