


Issue (Overview)

Customer input DC voltage to TLV07 via Multiplexer.
However, some samples (customer said 2pcs/12pcs samples) show unexpected output result.
Please confirm detail on next slide.

Summary




Input 1	+100mV
Input 2	0mV
Input 3	-100mV
Input 4	0mV

Issue (Detail)

Expected output

When we change input condition as shown below

“Input1” -> “Input2” -> “Input3” -> “Input4”



Some sample shows “unexpected” output :

When we change input condition as shown below

“Input1” -> “Input2” -> “Input3” -> “Input4”

