

UniFlash

UniFlash Session About Help Settings

Configured Device : Texas Instruments

Program

Settings & Utilities

Memory

Standalone Command Line

Flash Image: Please wait...

sensor_cc13x2lp_default.hex

Size: 273.16 KB | Binary:

Available

Load Image

Reset Action

[Click here to query available reset options]

Run Actions

Run Target After Program Load/Flash Operation

Console

Verbose Clear Close

[3/25/2020, 5:00:15 PM] [INFO] Cortex_M3_0: GEL Output: Memory Map Initialization Complete.
[3/25/2020, 5:00:16 PM] [INFO] Cortex_M4_0: GEL Output: Memory Map Initialization Complete.
[3/25/2020, 5:00:18 PM] [INFO] Cortex_M4_0: GEL Output: Board Reset Complete.
[3/25/2020, 5:00:22 PM] [INFO] Cortex_M4_0: Command=20 -- addr=0x00004800 -- length=0x00002000
[3/25/2020, 5:00:22 PM] [ERROR] Cortex_M4_0: File Loader: Memory write failed: Timed out waiting for target flashloader to execute command.

Finished

Cancel

Error!
File: C:/Users/VDO210919/Downloads/tidc01002-master (1)/tidc01002-master/prebuilt/CC13x2_LaunchPad/sensor_cc13x2_lp_default.hex:
Load failed.

Cortex_M4_0 Suspended

Windows Taskbar: 5:00 PM 3/25/2020

Configured Device : Texas Instruments XDS110 USB Debug Probe > CC1352R1F3 [\[more info\]](#) [\[download ccxml\]](#)

● Cortex_M4_0 Disconnected: Running

Program

Select and Load Images

Settings & Utilities

Flash Image(s)

sensor_cc13x2_lp_default.hex

Size: 273.16 KB | Binary: 

Available Action(s) - 1 Image Selected

Load Image

Verify Image

Reset Actions

[\[Click here to query available reset options\]](#)

Run Actions

 Run Target After Program Load/Flash Operation

☐ Console

🔊 Verbose

☰ Clear

✕ Close

[3/25/2020, 5:00:18 PM] [INFO] Cortex_M4_0: GEL Output: Board Reset Complete.

[3/25/2020, 5:00:22 PM] [INFO] Cortex_M4_0: Command=20 -- addr=0x00004800 -- length=0x00002000

[3/25/2020, 5:00:22 PM] [ERROR] Cortex_M4_0: File Loader: Memory write failed: Timed out waiting for target flashloader to execute command.

[3/25/2020, 5:01:10 PM] [ERROR] CS_DAP_0: Error: (Error -261 @ 0x0) Invalid response was received from the XDS110. (Emulation package 8.1.0.00007)

[3/25/2020, 5:01:11 PM] [ERROR] CS_DAP_0: Unable to determine target status after 20 attempts

[3/25/2020, 5:01:11 PM] [ERROR] CS_DAP_0: Failed to remove the debug state from the target before disconnecting. There may still be breakpoint op-codes embedded in program memory. It is recommended that you reset the emulator before you connect and reload your program before you continue debugging

[3/25/2020, 5:01:13 PM] [ERROR] Cortex_M4_0: ITAC Communication Error (Error -261 @ 0x0) Invalid response was received from the XDS110. (Emulation package 8.1.0.00007)

