

Flores, Teresa

From: Bell, Robert
Sent: Monday, October 31, 2011 3:23 PM
To: Flores, Teresa
Cc: Choudhary, Vijay
Subject: RE: Request for quote on 980600711-100A, LM5017EVAL 250pcs

2

Thanks

From: Flores, Teresa
Sent: Monday, October 31, 2011 3:07 PM
To: Bell, Robert
Cc: Choudhary, Vijay
Subject: Request for quote on 980600711-100A, LM5017EVAL 250pcs

Please select your assembly option and advise on item 3 below:

1)5 day parts and 5 day labor.

Material cost is \$6.87ea.

Labor cost is \$15.50ea.

Stencil cost is \$290.00.

Total cost is \$5882.50.

2)5 day parts and 10 day labor.

Material cost is \$6.87ea.

Labor cost is \$13.00ea.

Stencil cost is \$290.00.

Total cost is \$5257.50.

TI to provide:

1)PCBs and ICs.

2)Coilcraft SSR1260-221K

3)RT0603BRD0746K4L 46.4k ohm 0.1% can't find stock. Can it be crossed to 1%?