



BQ25890 Ship Mode

No VBUS



VSYS Stop is OK

VBUS ON



VSYS Non stop.
VSYS stop (ship mode) can after VBUS stop.
Is it correct?