

Synchronous operation is possible. However, there are cases where the duty is wide and narrow. What is the cause and how to fix it?

Vin=24V、Vout=5V、"RT Mode = $600kHz \rightarrow Sync Mode = 400kHz$ "、 Iout=No load