

DSO-X 3024A, MY54311009, Fri Oct 29 04:36:44 2021




Figure 1: Phihong AT, model no. POE29U-1AT(PL), zoomed in

DSO-X 3024A, MY54311009, Fri Oct 29 04:50:06 2021




Figure 2: Phihong AT, model no. POE29U-1AT(PL), zoomed out to match the remaining captures

DSO-X 3024A, MY54311009: Fri Oct 29 22:43:22 2021



Figure 3: Pihong AT, model no. POE29U-1AF

DSO-X 3024A, MY54311009: Fri Oct 29 22:49:39 2021




Figure 4: Trendnet Switch, model no. TPE-TG80g

DSO-X 3024A, MY54311009, Fri Oct 29 23:01:11 2021



Figure 5: BV Security PoE Switch, model no. poe-sw802-din

DSO-X 3024A, MY54311009: Fri Oct 29 23:06:53 2021




Figure 6: Zoomed in waveform of the delay before the detection