




**LMZ31707RVQ replace TPS40140RHHR
12V->5V**



**LMZ30606RKG replace TPS54617RUVR
5V->2.5V**



**LMZ31707RVQ replace TPS54550PWP
12V->3.3V**



**LMZ31707RVQ replace TPS40140RHHR
12V->0.9V**

