

Ch1 : +48V

Ch2 : VDD-RTN

Ch3 : Output
DCDC Converter

Ch4 : VSS Current

Although the voltage between
VSS and RTN
(between Drain and Source)
is rising, is there a problem
with the internal FET?

