File	Edit Vertical	Horiz/Acq	Trig Display	Cursors M	leasure Masl	k Math	MyScope	Analyze	Utilities	Help		19071516	Tek 📃 🔀
F	1 1 1 1					ه العالج	le 's i	9 	هر ماد	يوبعندنه	U U U	بعنصلي وتع	
		0	0										
													Curs1 X Pos 🧃
E					1							i x i x x x x	-8.58ms
E		n a h											Curs2 X Pos 🚯
2							-						-6.57ms
-		0 R 0										in fin of	
							Į				- 10		
•													
T		ю ж. (n i na nai
-		50.0%											- 0 0 0 0 0 0 0 -
1	e e e e l							1				1	
Å		ю ж i		а в) в в 	36 K) 36	ia os	· · + ·	9 A 6			e a e		-
Ť	i ci ci	ст с		1.61.7		, , ,	, ŧ,		i i	er ei	() (n in an	
ſ	C1) 900mV/di		1MO BW:500M		Roome-	1	-8.584ms		A' C2	● X 810mV		4.0ms/div 625N	IS/s 1.6ns/pt
	000mV/di 000mV/di		1MΩ ^B W:500M 1MΩ ^B W:500M		3.312V 2.16V	t2 At	-6.568ms					Stopped 51 acgs	RL:25.0M
	900mV/di		1MQ ^B W:500M		1.072kV/s	1/Δt		z				Man July 27,	
ſ		Value	Mean	Min	Max	St Dev	Count	Info				5	3
	C2 Rise	-5	189.59406µ	3.84n		40.48µ	24.0	۲]				
	C22 Fall	1.337ms	1.1050961m			552.5µ	28.0						
	Period	-S	13.6n	13.6n		0.0	1.0	۲					
	High	1.836V	1.7932349	108.0m		225.9m	51.0						
l	C1 Freq*	-Hz	104.1719M	5.152k	416.7M	208.3M	4.0	۲	J				

TPS65217B EVM: Good/correct power–off sequence.



TPS65217B EVM:No battery: Wrong power-off sequence due to inadvertently removing thepower to the EVM.