

**PDN# 20240404000.3**  
**Addendum for Discontinuance of Select Devices**  
**Product Notification**

**Date:** April 5, 2024

Dear Recipient:

You have been identified for notification of changes for one or more of the devices affected by the change detailed in this notice. You are being notified either because (1) of your recent purchase history of the affected devices or (2) you are listed as being part of GIDEP (Government-Industry Data Exchange Program).

The purpose of this addendum is to communicate a change in the end of life (EOL) status of select devices manufactured in SFAB or DFAB. To best support production needs for the duration of customers' existing project lifecycles, **devices listed starting on page 2 of this notice will remain orderable, and will no longer have a last-time buy date**. Here is what this means for you:

- You may continue to purchase these devices through your usual ordering process.
- There is no longer a last-time buy date for these devices. If the respective PDN has already expired and/or if you have already placed a last-time buy order, you may continue purchasing devices through your usual process beyond the previously stated last-time buy date.
- If you have any questions regarding existing backlog, please contact your local TI sales representative.

We know that semiconductor product longevity and supply continuity are important to you. We hope this update reiterates how important they are to us as well, and our ongoing efforts to meet customer needs. We are proud to serve as your reliable supplier, with inventory and manufacturing strategies that allow us to support your success for decades to come.

For questions regarding this notice, contact your local TI sales representative or our change management team.

Sincerely,

Change Management Team  
SC Business Services

**20240404000.3**  
**Attachments1**

**Products Affected:**

According to our records, you have recently purchased the following devices which are impacted by this notice. The original PDN number(s) are listed, and the corresponding customer part number is also listed, if available.

<b>PDN</b>	<b>DEVICE</b>	<b>CUSTOMER PART NUMBER</b>
20220614001.3	TLV810MDBZR	NULL
20220614001.3	TLV810RDBZR	NULL
20220614001.3	TLV810RDBZT	NULL
20221011001.3	LP2980IM5-2.5/NOPB	NULL
20221011001.3	LP2980IM5-3.8/NOPB	NULL
20221011001.3	LP2980IM5-4.7/NOPB	NULL
20221011001.3	LP2981-28DBVR	NULL
20221011001.3	LP2981AIM5-2.5/NOPB	NULL
20221011001.3	LP2981AIM5-3.0/NOPB	NULL
20221011001.3	LP2981AIM5X-3.0/NOPB	NULL
20221011001.3	LP2981IM5-2.5/NOPB	NULL
20221011001.3	LP2981IM5-3.0/NOPB	NULL
20221011001.3	LP2982AIM5-3.0/NOPB	NULL
20221011001.3	LP2982IM5-3.0/NOPB	NULL
20221011001.3	LP2983AIM5-1.0/NOPB	NULL
20221011001.3	LP2983AIM5-1.2/NOPB	NULL
20221011001.3	LP2983IM5-1.0/NOPB	NULL
20221011001.3	LP2983IM5-1.2/NOPB	NULL
20221011001.3	LP2985-29DBVR	NULL
20221011001.3	LP2985AIM5-1.5/NOPB	NULL
20221011001.3	LP2985AIM5-2.0/NOPB	NULL
20221011001.3	LP2985AIM5-2.7/NOPB	NULL
20221011001.3	LP2985AIM5-2.9/NOPB	NULL
20221011001.3	LP2985AIM5-3.1/NOPB	NULL
20221011001.3	LP2985IM5-2.7/NOPB	NULL
20221011001.3	LP2985IM5-2.9/NOPB	NULL
20221011001.3	LP2985IM5-3.2/NOPB	NULL
20221011001.3	LP2985IM5-5.7/NOPB	NULL
20221011001.3	LP2985IM5-6.1/NOPB	NULL
20221011001.3	LP2985IM5X-2.0/NOPB	NULL
20221011001.3	LP2985IM5X-2.7/NOPB	NULL
20221011001.3	LP2985IM5X-3.6/NOPB	NULL
20221011001.3	LP2989AIM-3.3/NOPB	NULL
20221011001.3	LP2989AIMM-2.5/NOPB	NULL
20221011001.3	LP2989AIMM-3.3/NOPB	NULL
20221011001.3	LP2989AIMX-5.0/NOPB	NULL
20221011001.3	LP2989ILD-2.5/NOPB	NULL
20221011001.3	LP2989ILD-3.0/NOPB	NULL
20221011001.3	LP2989ILD-5.0/NOPB	NULL
20221011001.3	LP2989IM-2.5/NOPB	NULL
20221011001.3	LP2989IM-3.3/NOPB	NULL
20221011001.3	LP2989IM-5.0/NOPB	NULL
20221011001.3	LP2989IMM-3.3/NOPB	NULL
20221011001.3	LP2989IMX-2.5/NOPB	NULL
20221011001.3	LP2989IMX-3.3/NOPB	NULL
20221011001.3	LP2992AIM5-1.5/NOPB	NULL
20221011001.3	LP2992AIM5X-1.8/NOPB	
20221011001.3	LP2992AIM5X-1.8/NOPB	NULL

20221011001.3	LP2992IM5-1.5/NOPB	NULL
20221011001.3	LP2992IM5-3.0/NOPB	NULL
20221011001.3	REG1117-2.85	NULL
20221011001.3	REG1117A	NULL
20221011001.3	REG1117F-3.3/500	NULL
20221011001.3	SN1603836DBVR	NULL
20221011001.3	TL1963A-15DCQT	NULL
20221011001.3	TL1963A-18KTTR	NULL
20221011001.3	TL1963A-25DCQT	NULL
20221011001.3	TL1963A-25DCYR	NULL
20221011001.3	TL1963A-25DCYT	NULL
20221011001.3	TL780-05CKTTR	NULL
20221011001.3	TLV1117-15IKVURG3	NULL
20221011001.3	TLV1117-18IKVURG3	NULL
20221011001.3	TPS7301QD	NULL
20221011001.3	TPS73215DBVR	NULL
20221011001.3	TPS7350QD	NULL
20221011001.3	TPS73615DCQR	NULL
20221011001.3	TPS73643DBVR	NULL
20221011001.3	TPS74201RGRR	NULL
20221011001.3	TPS76327DBVR	NULL
20221011001.3	TPS76328DBVT	NULL
20221011001.3	TPS76601D	NULL
20221011001.3	TPS76927DBVR	NULL
20221011001.3	TPS77012DBVT	NULL
20221011001.3	TPS77318DGK	NULL
20221011001.3	TPS79418DCQR	NULL
20221011001.3	TPS79428DGNT	NULL
20221011001.3	TPS79530DCQR	NULL
20221011001.3	TPS79625KTTR	NULL
20221011001.3	TPS79630DCQR	NULL
20221011001.3	TPS7A4525KTTR	NULL
20221011001.3	UA7808CKCS	NULL
20221011001.3	UA7815CKTTR	NULL
20221011001.3	UA7824CKCS	NULL
20221011001.3	UA78L02ACLP	NULL
20221011001.3	UA78L05CLP	NULL
20221011001.3	UA78L06ACLP	NULL
20221011001.3	UA78L08ACD	NULL
20221011001.3	UA78L08ACLP	NULL
20221011001.3	UA78L12ACLP	NULL
20221011001.3	UA78L15ACD	NULL
20221011001.3	UA78L15ACLP	NULL
20221011001.3	UA78M05CKCS	NULL
20221011001.3	UA78M05IKCS	NULL
20221011001.3	UA78M12CKCS	NULL
20230228006.3	THS3091D	NULL
20230228006.3	THS3091DR	NULL
20230315000.3	GD65232DW	NULL
20230315000.3	GD65232DWR	NULL
20230315000.3	GD75232DW	NULL
20230315000.3	GD75232DWR	NULL
20230315000.3	GD75323DW	NULL
20230315000.3	GD75323DWR	NULL
20230315000.3	LT1030CD	NULL
20230315000.3	LT1030CDR	NULL
20230315000.3	MAX3223IDW	NULL
20230315000.3	MAX3223IDWR	NULL
20230315000.3	MAX3318EIDBR	NULL

20230315000.3	SN65C1154N	NULL
20230315000.3	SN65C23243DGGR	NULL
20230315000.3	SN65C3222DBR	NULL
20230315000.3	SN65C3223DBR	NULL
20230315000.3	SN65C3223EDBR	NULL
20230315000.3	SN65C3223EDW	NULL
20230315000.3	SN65C3232DW	NULL
20230315000.3	SN65C3232EDWR	NULL
20230315000.3	SN65C3243DW	NULL
20230315000.3	SN65C3243DWR	NULL
20230315000.3	SN75150P	NULL
20230315000.3	SN75154D	NULL
20230315000.3	SN75155P	NULL
20230315000.3	SN75188N	NULL
20230315000.3	SN75188NSR	NULL
20230315000.3	SN75189AN	NULL
20230315000.3	SN75189ANSR	NULL
20230315000.3	SN75189D	NULL
20230315000.3	SN75189DR	NULL
20230315000.3	SN75189N	NULL
20230315000.3	SN75189NSR	NULL
20230315000.3	SN75C1154DWR	NULL
20230315000.3	SN75C1154N	NULL
20230315000.3	SN75C1406D	NULL
20230315000.3	SN75C1406DR	NULL
20230315000.3	SN75C1406DW	NULL
20230315000.3	SN75C1406DWR	NULL
20230315000.3	SN75C1406N	NULL
20230315000.3	SN75C185N	NULL
20230315000.3	SN75C188D	NULL
20230315000.3	SN75C188DR	NULL
20230315000.3	SN75C188N	NULL
20230315000.3	SN75C189N	NULL
20230315000.3	SN75C198N	NULL
20230315000.3	SN75C3222DWR	NULL
20230315000.3	SN75C3223EDB	NULL
20230315000.3	SN75C3232DW	NULL
20230315000.3	SN75C3232EDW	NULL
20230315000.3	SN75C3232EDWR	NULL
20230315000.3	SN75C3243DW	NULL
20230315000.3	SN75LBC241DWR	NULL
20230315000.3	SN75LP1185DWR	NULL
20230315000.3	TRSF3222ECDB	NULL
20230315000.3	TRSF3232IDWR	NULL
20230315000.3	TRSF3243IDB	NULL
20230315000.3	UA9636ACD	NULL
20230315000.3	UA9636ACP	NULL
20230324002.3	PCA9518DBR	NULL
20230324002.3	PCA9534ADGVR	NULL
20230324002.3	PCA9534DB	NULL
20230324002.3	PCA9534DGVR	NULL
20230324002.3	PCA9535DBQR	NULL
20230324002.3	PCA9535DGVR	NULL
20230324002.3	PCA9535DW	NULL
20230324002.3	PCA9535RTWR	NULL
20230324002.3	PCA9538DGVR	NULL
20230324002.3	PCA9538DW	NULL
20230324002.3	PCA9538DWR	NULL
20230324002.3	PCA9539DB	NULL

20230324002.3	PCA9539DBQR	NULL
20230324002.3	PCA9539DW	NULL
20230324002.3	PCA9544ADW	NULL
20230324002.3	PCA9544ADWR	NULL
20230324002.3	PCA9546ADW	NULL
20230324002.3	PCA9546ADWR	NULL
20230324002.3	PCA9548ADGVR	NULL
20230324002.3	PCA9548ADW	NULL
20230324002.3	PCA9555DGVR	NULL
20230330002.3	SN65LBC031D	NULL
20230330002.3	SN65LBC031DG4	NULL
20230330002.3	SN65LBC031DRG4	NULL
20230330002.3	SN75LBC031D	NULL
20230330002.3	SN75LBC031DR	NULL
20230330004.3	TLC271ACD	NULL
20230330004.3	TLC271AID	NULL
20230330004.3	TLC271BCD	NULL
20230330004.3	TLC271BID	NULL
20230330004.3	TLC271CD	NULL
20230330004.3	TLC271ID	NULL
20230413000.3	TPS54310QPWPRQ1	
20230413000.3	TPS54310QPWPRQ1	
20230413000.3	TPS54310QPWPRQ1	NULL
20230413000.3	TPS54316QPWPRQ1	NULL
20230413000.3	TPS54317RHFR	NULL
20230413000.3	TPS54610QPWPRG4Q1	
20230413000.3	TPS54610QPWPRG4Q1	
20230413000.3	TPS54610QPWPRG4Q1	NULL
20230413000.3	TPS54612QPWPRQ1	NULL
20230413000.3	TPS54616QPWPRQ1	NULL
20230413000.3	TPS54617RUVT	NULL
20230413000.3	TPS54810PWP	NULL
20230413000.3	TPS54810PWPR	NULL
20230413001.3	TPS61107PW	NULL
20230413001.3	TPS61107RGER	NULL
20230413001.3	TPS61120PW	NULL
20230413001.3	TPS61120PWR	NULL
20230413001.3	TPS61120RSAR	NULL
20230420001.3	PCA9534ADBR	NULL
20230420001.3	PCA9534ARGVR	NULL
20230420001.3	PCA9534DBR	NULL
20230420001.3	PCA9539DBR	NULL
20230420001.3	PCA9539DWR	NULL
20230420001.3	PCA9546ARGYR	NULL
20230420001.3	PCA9548ADWR	NULL
20230420001.3	PCA9555DW	NULL
20230503002.3	PCA9557DBR	NULL
20230503002.3	PCA9557DGVR	NULL
20230503002.3	PCA9557RGYR	NULL
20230503002.3	PCF8574ADGVR	NULL
20230503002.3	PCF8574DGVR	NULL
20230503002.3	PCF8575CDB	NULL
20230503002.3	PCF8575CDBR	NULL
20230503002.3	PCF8575CDW	NULL
20230503002.3	PCF8575CDWR	NULL
20230503002.3	PCF8575CPW	NULL
20230503002.3	PCF8575CPWR	NULL
20230503002.3	PCF8575DBQR	NULL
20230503002.3	PCF8575DGVR	NULL

20230505000.3	DS14C88M/NOPB	NULL
20230505000.3	DS14C89AM/NOPB	NULL
20230505000.3	MAX208CDW	NULL
20230505000.3	MAX208CDWR	NULL
20230505000.3	MAX208IDW	NULL
20230505000.3	MAX208IDWR	NULL
20230505000.3	MAX213IDWR	NULL
20230505000.3	MAX3238IPWQ1	NULL
20230505000.3	SN65C3232DBR	NULL
20230505000.3	SN75C3232DBR	NULL
20230505000.3	TRS202ECDWR	NULL
20230505000.3	TRS202ECN	NULL
20230505000.3	TRS202EIDW	NULL
20230505000.3	TRS202EIN	NULL
20230505000.3	TRS208CDWR	NULL
20230505000.3	TRS208IDWR	NULL
20230505000.3	TRS213IDWR	NULL
20230505000.3	TRSF3232ECDBR	NULL
20230505000.3	TRSF3232EIDBR	NULL
20230516001.3	AM26C31CN	NULL
20230516001.3	AM26C32CN	NULL
20230516001.3	AM26C32IN	NULL
20230516001.3	AM26LS31CDBR	NULL
20230516001.3	AM26LS31INSR	NULL
20230516001.3	AM26LS32AIN	NULL
20230516001.3	AM26LS33ACN	NULL
20230516001.3	AM26S10CD	NULL
20230516001.3	DS36954M/NOPB	NULL
20230516001.3	MC3486N	NULL
20230516001.3	MC3487N	NULL
20230516001.3	MC3487NSR	NULL
20230516001.3	SN103144DR	
20230516001.3	SN65175D	NULL
20230516001.3	SN65175DR	NULL
20230516001.3	SN65C1168N	NULL
20230516001.3	SN65HVD06P	NULL
20230516001.3	SN65HVD08P	NULL
20230516001.3	SN65HVD11P	NULL
20230516001.3	SN65HVD12P	NULL
20230516001.3	SN65HVD21P	NULL
20230516001.3	SN65LBC171DWR	NULL
20230516001.3	SN65LBC172DW	NULL
20230516001.3	SN65LBC176AP	NULL
20230516001.3	SN65LBC176P	NULL
20230516001.3	SN65LBC179AP	NULL
20230516001.3	SN65LBC179P	NULL
20230516001.3	SN65LBC180AN	NULL
20230516001.3	SN65LBC180N	NULL
20230516001.3	SN75107AD	NULL
20230516001.3	SN75107AN	NULL
20230516001.3	SN75107BDR	NULL
20230516001.3	SN75108AD	NULL
20230516001.3	SN75110AN	NULL
20230516001.3	SN75113N	NULL
20230516001.3	SN75114N	NULL
20230516001.3	SN75115D	NULL
20230516001.3	SN75115DR	NULL
20230516001.3	SN75115N	NULL
20230516001.3	SN75121N	NULL

20230516001.3	SN75123N	NULL
20230516001.3	SN75124N	NULL
20230516001.3	SN75138N	NULL
20230516001.3	SN75138NSR	NULL
20230516001.3	SN75159D	NULL
20230516001.3	SN75159N	NULL
20230516001.3	SN75160BDW	NULL
20230516001.3	SN75160BN	NULL
20230516001.3	SN75161BDW	NULL
20230516001.3	SN75161BN	NULL
20230516001.3	SN75162BDW	NULL
20230516001.3	SN75162BDWR	NULL
20230516001.3	SN75176AP	NULL
20230516001.3	SN75178BP	NULL
20230516001.3	SN75182N	NULL
20230516001.3	SN75183N	NULL
20230516001.3	SN75207BN	NULL
20230516001.3	SN7534051NS	NULL
20230516001.3	SN75ALS160N	NULL
20230516001.3	SN75ALS161DW	NULL
20230516001.3	SN75ALS161DWR	NULL
20230516001.3	SN75ALS162DW	NULL
20230516001.3	SN75ALS174AN	NULL
20230516001.3	SN75ALS174APWR	NULL
20230516001.3	SN75ALS176AP	NULL
20230516001.3	SN75ALS176BP	NULL
20230516001.3	SN75ALS176P	NULL
20230516001.3	SN75ALS180N	NULL
20230516001.3	SN75ALS181N	NULL
20230516001.3	SN75ALS192N	NULL
20230516001.3	SN75ALS194N	NULL
20230516001.3	SN75ALS195N	NULL
20230516001.3	SN75ALS199DR	NULL
20230516001.3	SN75C1167N	NULL
20230516001.3	SN75C1168N	NULL
20230516001.3	SN75HVD08P	NULL
20230516001.3	SN75LBC170DB	NULL
20230516001.3	SN75LBC172N	NULL
20230516001.3	SN75LBC174ADW	NULL
20230516001.3	SN75LBC174ADWR	NULL
20230516001.3	SN75LBC174N	NULL
20230516001.3	SN75LBC175N	NULL
20230516001.3	SN75LBC176AP	NULL
20230516001.3	SN75LBC176P	NULL
20230516001.3	SN75LBC179P	NULL
20230516001.3	SN75LBC180AN	NULL
20230516001.3	SN75LBC180N	NULL
20230516001.3	TL3695D	NULL
20230516001.3	TL3695DR	NULL
20230516001.3	TL3695P	NULL
20230516001.3	UA9637ACP	NULL
20230516001.3	UA9639CP	NULL
20230525001.3	THS6226IRHBR	NULL
20230525001.3	THS6226IRHBT	NULL
20230531001.3	TPS73028DBVR	NULL
20230531001.3	TPS731125DBVR	NULL
20230531001.3	TPS73131DBVR	NULL
20230531001.3	TPS73132DBVR	NULL
20230531001.3	TPS73213DBVR	NULL

20230531001.3	TPS73225DCQR	NULL
20230531001.3	TPS73230DCQR	NULL
20230531001.3	TPS736125DRBR	NULL
20230531001.3	TPS73615DRBR	NULL
20230531001.3	TPS73619DRBR	NULL
20230531001.3	TPS73630DCQR	NULL
20230531001.3	TPS74201KTWR	NULL
20230531001.3	TPS74201RGWRAU	NULL
20230531001.3	TPS74401KTWR	NULL
20230531001.3	TPS74401RGRR	NULL
20230531001.3	TPS79101DBVR	NULL
20230531001.3	TPS79101DBVRQ1	NULL
20230531001.3	TPS79118DBVR	NULL
20230531001.3	TPS79133DBVR	NULL
20230531001.3	TPS79147DBVR	NULL
20230531001.3	TPS79225DBVR	NULL
20230531001.3	TPS793285DBVR	NULL
20230531001.3	TPS79330QDBVRQ1	NULL
20230531001.3	TPS793475DBVR	NULL
20230531001.3	TPS79433DCQR	NULL
20230531001.3	TPS79618KTTR	NULL
20230531001.3	TPS79630KTTR	NULL
20230613002.3	SN74HC4851D	NULL
20230613002.3	SN74HC4851DR	NULL
20230613002.3	SN74HC4851N	NULL
20230613002.3	SN74HC4851PW	NULL
20230613002.3	SN74HC4851PWRG4	NULL
20230613002.3	SN74HC4851QDRQ1	NULL
20230613002.3	SN74HC4851QPWRG4Q1	NULL
20230613002.3	SN74HC4851QPWRRBG4	
20230613002.3	SN74HC4851QPWRRBG4	NULL
20230613002.3	SN74HC4852D	NULL
20230613002.3	SN74HC4852DGVR	NULL
20230613002.3	SN74HC4852DR	NULL
20230613002.3	SN74HC4852QDRQ1	NULL
20230616000.3	TL16C450FN	NULL
20230616000.3	TL16C450FNR	NULL
20230616000.3	TL16C452FN	NULL
20230616000.3	TL16C452FNR	NULL
20230616000.3	TL16C552AFN	NULL
20230616000.3	TL16C552AIFN	NULL
20230616000.3	TL16C552FN	NULL
20230616000.3	TL16C750FN	NULL
20230616000.3	TL16C750FNR	NULL
20230616000.3	TL16C754BFN	NULL
20230616000.3	TL16C754BPN	NULL
20230616000.3	TL16C754BPNR	NULL
20230619003.3	LM224ADRG4	NULL
20230619003.3	LM2901DRG4	NULL
20230619003.3	LM2902DRG4	NULL
20230619003.3	LM2902PWRG4	NULL
20230619003.3	LM324DRG4	NULL
20230619003.3	LM324PWRG4	NULL
20230619003.3	LM339DRE4	NULL
20230619003.3	LM339DRG4	NULL
20230619003.3	LM339PWRG4	NULL
20230619003.3	NE5532DRG4	NULL
20230621003.3	ISO7230MDWR	NULL
20230621005.3	CD4016BPW	NULL



20230621005.3	CD4016BPWR	NULL
20230621005.3	CD4053BQM96G4Q1	NULL
20230621005.3	CD4053BQM96Q1	NULL
20230621005.3	CD4066BQDRQ1	NULL
20230621005.3	CD4097BPWR	NULL
20230621005.3	CD74HC4016E	NULL
20230621005.3	CD74HC4016M96	NULL
20230621005.3	CD74HC4016MT	NULL
20230621005.3	CD74HC4016PW	NULL
20230621005.3	CD74HC4052E	NULL
20230621005.3	CD74HC4053E	NULL
20230621005.3	CD74HC4066E	NULL
20230621005.3	CD74HC4316E	NULL
20230621005.3	CD74HC4351E	NULL
20230621005.3	CD74HCT4051E	NULL
20230621005.3	CD74HCT4052E	NULL
20230621005.3	CD74HCT4053E	NULL
20230621005.3	CD74HCT4066E	NULL
20230621005.3	CD74HCT4316E	NULL
20230621005.3	CD74HCT4316M	NULL
20230621005.3	CD74HCT4316M96	NULL
20230621005.3	MSA00084DBVR	
20230621005.3	MSA00084DBVR	
20230621005.3	SN74AHC4066DGVR	NULL
20230621005.3	SN74CBT16209ADGVR	NULL
20230621005.3	SN74CBT16211ADGVR	NULL
20230621005.3	SN74CBT16214DGGR	NULL
20230621005.3	SN74CBT16214DLR	NULL
20230621005.3	SN74CBT16244DGGR	NULL
20230621005.3	SN74CBT16292DGVR	NULL
20230621005.3	SN74CBT16861DGVR	NULL
20230621005.3	SN74CBT1G125DBVT	NULL
20230621005.3	SN74CBT1G384DCKR	NULL
20230621005.3	SN74CBT3125DBQR	NULL
20230621005.3	SN74CBT3126D	NULL
20230621005.3	SN74CBT3126DR	NULL
20230621005.3	SN74CBT3251D	NULL
20230621005.3	SN74CBT3251DBQR	NULL
20230621005.3	SN74CBT3251PW	NULL
20230621005.3	SN74CBT3383DWR	NULL
20230621005.3	SN74CBT3383PW	NULL
20230621005.3	SN74CBT3383PWR	NULL
20230621005.3	SN74CBT3384ADW	NULL
20230621005.3	SN74CBT3384ADWR	NULL
20230621005.3	SN74CBTD16210DGVR	NULL
20230621005.3	SN74CBTD16210DL	NULL
20230621005.3	SN74CBTD16211DL	NULL
20230621005.3	SN74CBTD1G125DCKR	NULL
20230621005.3	SN74CBTD1G125DCKT	NULL
20230621005.3	SN74CBTD3861DBR	NULL
20230621005.3	SN74CBTD3861DGVR	NULL
20230621005.3	SN74CBTD3861DW	NULL
20230621005.3	SN74CBTD3861DWR	NULL
20230621005.3	SN74CBTD3861PW	NULL
20230621005.3	SN74CBTS16211DGGR	NULL
20230621005.3	SN74CBTS3306PWR	NULL
20230621005.3	SN74HC4066DBR	NULL
20230621005.3	SN74HC4066N	NULL
20230621005.3	SN74HC4066NSR	NULL

20230621005.3	SN74LV4051ADBR	NULL
20230621005.3	SN74LV4051AN	NULL
20230621005.3	SN74LV4051ANSR	NULL
20230621005.3	SN74LV4051ATDRQ1	NULL
20230621005.3	SN74LV4051ATDWRQ1	NULL
20230621005.3	SN74LV4052ADBR	NULL
20230621005.3	SN74LV4052ADGVR	NULL
20230621005.3	SN74LV4052AN	NULL
20230621005.3	SN74LV4052ANSR	NULL
20230621005.3	SN74LV4053ADBR	NULL
20230621005.3	SN74LV4053ATDRQ1	NULL
20230621005.3	SN74LV4066ADBR	NULL
20230621005.3	SN74LV4066ADGVR	NULL
20230621005.3	SN74LV4066ANSR	NULL
20230621005.3	SN74TVC16222ADGGR	NULL
20230621005.3	SN74TVC16222ADGVR	NULL
20230621005.3	SN74TVC3010DBQR	NULL
20230621005.3	SN74TVC3010DGVR	NULL
20230621005.3	SN74TVC3010PW	NULL
20230621005.3	SN74TVC3010PWR	NULL
20230621005.3	TS5L100DBQR	NULL
20230621005.3	TS5V330DR	NULL
20230622000.3	LM258ADRG4	NULL
20230622000.3	LP324DRG4	NULL
20230627000.3	REG711EA-2.5/250	NULL
20230627000.3	REG711EA-2.5/2K5	NULL
20230627000.3	REG711EA-3.3/250	NULL
20230627000.3	REG711EA-3/2K5	NULL
20230627000.3	REG711EA-5/250	NULL
20230627000.3	REG711EA-5/2K5	NULL
20230627000.3	TPS60240DGKR	NULL
20230627000.3	TPS60240DGKT	NULL
20230627000.3	TPS60243DGKR	NULL
20230627000.3	TPS61031PWPR	NULL
20230627000.3	TPS61032PWP	NULL
20230627000.3	TPS61032PWPR	NULL
20230627000.3	TPS61032RSAR	NULL
20230627000.3	TPS61091RSAR	NULL
20230627000.3	TPS61100PW	NULL
20230627000.3	TPS61100PWR	NULL
20230627000.3	TPS61202DSCR	NULL
20230627000.3	TPS61202D SCT	NULL
20230627003.3	SN74CBT16210DGVR	NULL
20230627003.3	SN74CBT3253D	NULL
20230627003.3	SN74CBT3384APW	NULL
20230707000.3	CD74HC4351M96	NULL
20230707000.3	SN74CBT16209ADL	NULL
20230707000.3	SN74CBT16212ADGGR	NULL
20230707000.3	SN74CBT16212ADL	NULL
20230707000.3	SN74CBT1G125DCKT	NULL
20230707000.3	SN74CBT3126PW	NULL
20230707000.3	SN74CBT3383DW	NULL
20230707000.3	SN74CBT3861DW	NULL
20230707000.3	SN74CBTD1G125DBVT	NULL
20230707000.3	SN74CBTD3384DBR	NULL
20230707000.3	SN74CBTS3306DR	NULL
20230707000.3	SN74TVC16222ADL	NULL
20230707000.3	SN74TVC16222ADLR	NULL
20230707000.3	TS12A4514P	NULL

20230721000.3	SN75161BDWR	NULL
20230721000.3	SN75ALS162DWR	NULL
20230725002.3	SN65HVD21AD	NULL
20230725002.3	SN65HVD21ADR	NULL
20230731000.3	SN75240P	NULL
20230731000.3	UC3610DW	NULL
20230731000.3	UC3610DWTR	NULL
20230731000.3	UC3610N	NULL
20230731000.3	UC3611DW	NULL
20230731000.3	UC3611N	NULL
20230808001.3	TPS40001DGQR	NULL
20230808001.3	TPS40020PWP	NULL
20230808001.3	TPS40021PWP	NULL
20230808001.3	TPS54073PWP	NULL
20230808001.3	TPS54073PWPG4	NULL
20230808001.3	TPS54110PWPR	NULL
20230808001.3	TPS54373PWP	NULL
20230808001.3	TPS54380PWPR	NULL
20230808001.3	TPS54673PWP	NULL
20230808001.3	TPS54673PWPR	NULL
20230808001.3	TPS54680PWPR	NULL
20230808001.3	TPS54873PWP	NULL
20230808001.3	TPS54873PWPR	NULL
20230808001.3	TPS54910PWPR	NULL
20230808001.3	TPS54973PWP	NULL
20230808001.3	TPS54980PWP	NULL
20230808001.3	TPS54980PWPR	NULL
20230808001.3	TPS56100PWP	NULL
20230808001.3	TPS56300PWP	NULL
20230808001.3	TPS62000SHKK	NULL
20230817000.3	TPS5450DDA	NULL
20230817000.3	TPS5450DDAR	NULL
20230817000.3	TPS5450DDARG4	NULL
20230817000.3	TPS5450QDDARQ1	NULL
20230818001.3	TPS51163DRCR	NULL
20230818001.3	TPS51163DRCT	NULL
20230818001.3	TPS54120RGYR	NULL
20230818001.3	TPS54120RGYT	NULL
20230818001.3	TPS54352PWP	NULL
20230818001.3	TPS54353PWP	NULL
20230818001.3	TPS54353PWPR	NULL
20230818001.3	TPS54356PWP	NULL
20230818001.3	TPS54356PWPR	NULL
20230818001.3	TPS54357PWP	NULL
20230818001.3	TPS54357PWPR	NULL
20230818001.3	TPS55383PWPR	NULL
20230830004.3	5962-9959101Q2A	NULL
20230830004.3	5962-9962001Q2A	NULL
20230830004.3	TL1431MFKB	NULL
20230830004.3	TPS3307-18MFKB	NULL
20230830004.3	TPS3307-18MJGB	NULL
20230831000.3	TLC7733MPWREP	NULL
20230831000.3	TPS3836L30MDBVREP	NULL
20230831001.3	TPS3837K33DBVTG4	NULL
20230905002.3	LM3411M5-3.3/NOPB	NULL
20230905002.3	LM3411M5-5.0/NOPB	NULL
20230905002.3	LM3411M5X-3.3/NOPB	NULL
20230905002.3	LM3411M5X-5.0/NOPB	NULL
20230905002.3	LM385BPWR-1-2	NULL

20230905002.3	LM385PWR-1-2	NULL
20230905002.3	LM4040AIZ-10.0/NOPB	NULL
20230905002.3	LM4040BIZ-10.0/NOPB	NULL
20230905002.3	LM4040CIZ-10.0/NOPB	NULL
20230905002.3	LM4040DIZ-10.0/NOPB	NULL
20230905002.3	LM4040DIZ-5.0/LFT1	NULL
20230905002.3	LM4050QAIM3-10/NOPB	NULL
20230905002.3	REF1004C-1.2	NULL
20230905002.3	REF1004C-1.2/2K5	NULL
20230905002.3	REF1004C-2.5	NULL
20230905002.3	REF1004C-2.5/2K5	NULL
20230905002.3	REF1004I-1.2	NULL
20230905002.3	REF1004I-1.2/2K5	NULL
20230905002.3	REF1004I-2.5	NULL
20230905002.3	REF1004I-2.5/2K5	NULL
20230905002.3	SNV431BQDBZR	NULL
20230905002.3	TL1431MFK	NULL
20230905002.3	TL431CDR-J	NULL
20230905002.3	TL431CLP-Z	NULL
20230905002.3	TL7759CPWR	NULL
20230905002.3	TLC7701QP	NULL
20230905002.3	TLC7703QPW	NULL
20230905002.3	TLC7705IP	NULL
20230905002.3	TLC7705MJG	NULL
20230905002.3	TLC7725QD	NULL
20230905002.3	TLC7733IP	NULL
20230905002.3	TLC7733MJG	NULL
20230905002.3	TLV431ACLP	NULL
20230905002.3	TLV431ACLPR	NULL
20230905002.3	TLV431AIDR	NULL
20230905002.3	TLV431AILPR	NULL
20230905002.3	TLV431BILPR	NULL
20230905002.3	TLV431BQLPR	NULL
20230905002.3	TLV431ILPR	NULL
20230905002.3	TLVH431BILP	NULL
20230905002.3	TLVH431BILPR	NULL
20230905002.3	TLVH431BQLPR	NULL
20230905002.3	TPS3306-20D	NULL
20230905002.3	TPS3511DR	NULL
20230905002.3	TPS3513DR	NULL
20230905002.3	TPS3514DR	NULL
20230905002.3	TPS3606-33DGS	NULL
20230905002.3	TPS3606-33DGSR	NULL
20230905002.3	TPS3610T50PWR	NULL
20230905002.3	TPS3610U18PW	NULL
20230905002.3	TPS3800G27DCKR	NULL
20230905002.3	TPS3837K33DBVR	NULL
20230905002.3	TPS3837K33DBVT	NULL
20230905002.3	TPS3837L30DBVR	NULL
20230905003.3	TLV1117LV12DCYR	NULL
20230905003.3	TLV1117LV15DCYR	NULL
20230905003.3	TLV117112DCYR	NULL
20230905003.3	TPS70302PWPR	NULL
20230905003.3	TPS72501KTTR	NULL
20230905003.3	TPS72515DCQR	NULL
20230905003.3	TPS72525DCQR	NULL
20230905003.3	TPS72615DCQR	NULL
20230905003.3	TPS73047DBVR	NULL
20230905003.3	TPS75201QPWPRQ1	NULL

20230905003.3	TPS79428DCQR	NULL
20230905003.3	TPS79433DGNR	NULL
20230906005.3	SN1708006DR	NULL
20230906005.3	TLE2022AMDG4	NULL
20230907000.3	INA101AG	NULL
20230907000.3	INA101AM	NULL
20230907000.3	INA101CM	NULL
20230907000.3	INA101SM	NULL
20230907000.3	INA105AM	NULL
20230907000.3	INA105BM	NULL
20230907000.3	INA110SG	NULL
20230907000.3	INA117BM	NULL
20230907000.3	INA2134PA	NULL
20230907000.3	INA2137PA	NULL
20230907000.3	LDC6996AIMX/NOPB	NULL
20230907000.3	LM2902KDB	NULL
20230907000.3	LM2902NSR	NULL
20230907000.3	LM2904PSR	NULL
20230907000.3	LM324ANSR	NULL
20230907000.3	LM358PSR	NULL
20230907000.3	LM3900D	NULL
20230907000.3	LM393APSR	NULL
20230907000.3	LMC6022IM/NOPB	NULL
20230907000.3	LMC6022IMX/NOPB	NULL
20230907000.3	LMC6024IM/NOPB	NULL
20230907000.3	LMC6024IMX/NOPB	NULL
20230907000.3	LMC6032IN/NOPB	NULL
20230907000.3	LMC6081-MDA	NULL
20230907000.3	LMC6082AIN/NOPB	NULL
20230907000.3	LMC6082IN/NOPB	NULL
20230907000.3	LMC8101TP/NOPB	NULL
20230907000.3	LMC8101TPX/NOPB	NULL
20230907000.3	LP2902N	NULL
20230907000.3	LP339N	NULL
20230907000.3	LPC660AIM/NOPB	NULL
20230907000.3	LPC660AIMX/NOPB	NULL
20230907000.3	LPC660IMX/NOPB	NULL
20230907000.3	LPC662AIM/NOPB	NULL
20230907000.3	LPC662AIMX/NOPB	NULL
20230907000.3	LPC662IM/NOPB	NULL
20230907000.3	LPC662IMX/NOPB	NULL
20230907000.3	LT1014DIN	NULL
20230907000.3	LT1014DN	NULL
20230907000.3	MC1458PSR	NULL
20230907000.3	MPY100BG	NULL
20230907000.3	NE5532APSR	NULL
20230907000.3	NE5532PSR	NULL
20230907000.3	OP-07DP	NULL
20230907000.3	OP07DP	NULL
20230907000.3	OPA137U	NULL
20230907000.3	OPA2132P	NULL
20230907000.3	OPA2228P	NULL
20230907000.3	OPA2228PA	NULL
20230907000.3	OPA2241PA	NULL
20230907000.3	OPA2251PA	NULL
20230907000.3	OPA37GP	NULL
20230907000.3	OPA4131PA	NULL
20230907000.3	OPA4131PJ	NULL
20230907000.3	OPA4137P	NULL

20230907000.3	OPA4241PA	NULL
20230907000.3	OPA4277PA	NULL
20230907000.3	OPA445BM	NULL
20230907000.3	PGA204AP	NULL
20230907000.3	PGA204BP	NULL
20230907000.3	PGA205AP	NULL
20230907000.3	PGA205BP	NULL
20230907000.3	RC4558PSR	NULL
20230907000.3	SN2903DR	NULL
20230907000.3	THS3112ID	NULL
20230907000.3	THS3112IDDA	NULL
20230907000.3	THS3125CPWP	NULL
20230907000.3	THS4022ID	NULL
20230907000.3	THS6062ID	NULL
20230907000.3	TL031ID	NULL
20230907000.3	TL034AIN	NULL
20230907000.3	TL034CN	NULL
20230907000.3	TL034IN	NULL
20230907000.3	TL052CPSR	NULL
20230907000.3	TL054ACN	NULL
20230907000.3	TL072CPS	NULL
20230907000.3	TL072CPSR	NULL
20230907000.3	TL074CNSR	NULL
20230907000.3	TL082ACPSR	NULL
20230907000.3	TL082CPSR	NULL
20230907000.3	TL084ACNSR	NULL
20230907000.3	TL084CNSR	NULL
20230907000.3	TL092CPSR	NULL
20230907000.3	TL3474ACN	NULL
20230907000.3	TL3474AIN	NULL
20230907000.3	TL3474CN	NULL
20230907000.3	TL3474IN	NULL
20230907000.3	TL35072P	NULL
20230907000.3	TLC074CN	NULL
20230907000.3	TLC075CPWP	NULL
20230907000.3	TLC081CP	NULL
20230907000.3	TLC082IP	NULL
20230907000.3	TLC251ACP	NULL
20230907000.3	TLC251CD	NULL
20230907000.3	TLC251CP	NULL
20230907000.3	TLC252CD	NULL
20230907000.3	TLC252CP	NULL
20230907000.3	TLC254BCD	NULL
20230907000.3	TLC25L2CDR	NULL
20230907000.3	TLC25M2ACD	NULL
20230907000.3	TLC2652CN	NULL
20230907000.3	TLC2652Q-8D	NULL
20230907000.3	TLC2654C-14DR	NULL
20230907000.3	TLC2654C-8D	NULL
20230907000.3	TLC2654CN	NULL
20230907000.3	TLC271ACDR	NULL
20230907000.3	TLC271ACP	NULL
20230907000.3	TLC271AIDR	NULL
20230907000.3	TLC271AIP	NULL
20230907000.3	TLC271BCDR	NULL
20230907000.3	TLC271BCP	NULL
20230907000.3	TLC271BIDR	NULL
20230907000.3	TLC271CPSR	NULL
20230907000.3	TLC271CPWR	NULL

20230907000.3	TLC271IDR	NULL
20230907000.3	TLC271IP	NULL
20230907000.3	TLC271MDR	NULL
20230907000.3	TLC274ACN	NULL
20230907000.3	TLC274BCN	NULL
20230907000.3	TLC274CN	NULL
20230907000.3	TLC274IN	NULL
20230907000.3	TLC279CN	NULL
20230907000.3	TLC279IN	NULL
20230907000.3	TLC27L2ACP	NULL
20230907000.3	TLC27L2AIP	NULL
20230907000.3	TLC27L2BIP	NULL
20230907000.3	TLC27L2CPSR	NULL
20230907000.3	TLC27L2IP	NULL
20230907000.3	TLC27L7CP	NULL
20230907000.3	TLC27L7CPSR	NULL
20230907000.3	TLC27L7IP	NULL
20230907000.3	TLC27L9CN	NULL
20230907000.3	TLC27M2ACP	NULL
20230907000.3	TLC27M2AIP	NULL
20230907000.3	TLC27M2CP	NULL
20230907000.3	TLC27M2IP	NULL
20230907000.3	TLC27M2MD	NULL
20230907000.3	TLC27M4IN	NULL
20230907000.3	TLC339CN	NULL
20230907000.3	TLC339IN	NULL
20230907000.3	TLC352CP	NULL
20230907000.3	TLC354CD	NULL
20230907000.3	TLC354CN	NULL
20230907000.3	TLC354CPWR	NULL
20230907000.3	TLC354ID	NULL
20230907000.3	TLC3702CP	NULL
20230907000.3	TLC3702MJG	NULL
20230907000.3	TLC3704IN	NULL
20230907000.3	TLC372CPSR	NULL
20230907000.3	TLC372IP	NULL
20230907000.3	TLC372MP	NULL
20230907000.3	TLC393CP	NULL
20230907000.3	TLC393CPS	NULL
20230907000.3	TLC393CPSR	NULL
20230907000.3	TLC4501ACD	NULL
20230907000.3	TLC551CP	NULL
20230907000.3	TLC552CD	NULL
20230907000.3	TLC556MD	NULL
20230907000.3	TLE2021CP	NULL
20230907000.3	TLE2021IP	NULL
20230907000.3	TLE2021MD	NULL
20230907000.3	TLE2021MDG4	NULL
20230907000.3	TLE2022ACP	NULL
20230907000.3	TLE2022CP	NULL
20230907000.3	TLE2022IP	NULL
20230907000.3	TLE2024ACN	NULL
20230907000.3	TLE2024AIDW	NULL
20230907000.3	TLE2024CN	NULL
20230907000.3	TLE2037AMD	NULL
20230907000.3	TLE2037MD	NULL
20230907000.3	TLE2141AIP	NULL
20230907000.3	TLE2141CP	NULL
20230907000.3	TLE2141IP	NULL

20230907000.3	TLE2161AIDR	NULL
20230907000.3	TLE2425CD	NULL
20230907000.3	TLE2425CLP	NULL
20230907000.3	TLE2425ID	NULL
20230907000.3	TLE2425IDR	NULL
20230907000.3	TLE2425ILP	NULL
20230907000.3	TLE2426CDR	NULL
20230907000.3	TLE2426CP	NULL
20230907000.3	TLE2426ID	NULL
20230907000.3	TLE2426ILP	NULL
20230907000.3	TLE2426IP	NULL
20230907000.3	TLE2426MD	NULL
20230907000.3	TLV2254IN	NULL
20230907000.3	TLV2322IPWR	NULL
20230907000.3	TLV2324IN	NULL
20230907000.3	TLV2332IDR	NULL
20230907000.3	TLV2342IP	NULL
20230907000.3	TLV2422AIPWR	NULL
20230907000.3	TLV2422IDR	NULL
20230907000.3	TLV2432AQDRQ1	NULL
20230907000.3	TLV2455AID	NULL
20230907000.3	TLV2460ID	NULL
20230907000.3	TLV2620IDBVR	NULL
20230907000.3	TLV2620IDBVT	NULL
20230907000.3	TLV2621IDBVR	NULL
20230907000.3	TLV2621IDBVT	NULL
20230907000.3	TLV2622IDGKR	NULL
20230907000.3	TLV2623IDGSR	NULL
20230907000.3	TLV2624ID	NULL
20230907000.3	TLV2624IDR	NULL
20230907000.3	TLV2624IPWR	NULL
20230907000.3	TLV2631IDBVT	NULL
20230907000.3	TLV2632IDGKR	NULL
20230907000.3	TLV2632IDR	NULL
20230907000.3	TLV2634IPWR	NULL
20230907000.3	TLV2765CDR	NULL
20230907000.3	TLV2765IPW	NULL
20230907000.3	TLV2765IPWR	NULL
20230907000.3	TLV2770IDGKR	NULL
20230907000.3	TLV2770IDR	NULL
20230907000.3	TLV2771CD	NULL
20230907000.3	TLV2771IDR	NULL
20230907000.3	TLV2772AQDRQ1	NULL
20230907000.3	TLV2772AQPW	NULL
20230907000.3	TLV2774AIN	NULL
20230907000.3	TLV2775ID	NULL
20230907000.3	TLV3401CD	NULL
20230907000.3	TLV3701ID	NULL
20230907000.3	TLV3701IDR	NULL
20230907000.3	TLV3704ID	NULL
20230907000.3	TLV3704IDR	NULL
20230907000.3	TLV4110ID	NULL
20230907000.3	TLV4111CD	NULL
20230907000.3	TLV4113ID	NULL
20230907000.3	TLV4120IDGN	NULL
20230907000.3	UA741CPSR	NULL
20230907000.3	XTR101AG	NULL
20230907000.3	XTR101BG	NULL
20230907000.3	XTR105P	NULL



20230907000.3	XTR105PA	NULL
20230907000.3	XTR106P	NULL
20230907000.3	XTR106PA	NULL
20230907000.3	XTR110AG	NULL
20230907000.3	XTR110BG	NULL
20230907001.3	5962-9088101MPA	NULL
20230907001.3	INA122P	NULL
20230907001.3	INA122PA	NULL
20230907001.3	INA125P	NULL
20230907001.3	INA125PA	NULL
20230907001.3	INA128P	NULL
20230907001.3	INA128PA	NULL
20230907001.3	LM2900N	NULL
20230907001.3	LM324NSR	NULL
20230907001.3	LM6171BIN/NOPB	NULL
20230907001.3	LM6172IN/NOPB	NULL
20230907001.3	LM7171BIN/NOPB	NULL
20230907001.3	LMC6035ITL/NOPB	NULL
20230907001.3	LMC6035ITLX/NOPB	NULL
20230907001.3	LMC6081IN/NOPB	NULL
20230907001.3	LMC6482M MD8	NULL
20230907001.3	LMC662AIN/NOPB	NULL
20230907001.3	LMC662CN/NOPB	NULL
20230907001.3	LP324N	NULL
20230907001.3	OPA2132PA	NULL
20230907001.3	OPA2134PA	NULL
20230907001.3	OPA2227P	NULL
20230907001.3	OPA2227PA	NULL
20230907001.3	OPA2244PA	NULL
20230907001.3	OPA227P	NULL
20230907001.3	OPA227PA	NULL
20230907001.3	OPA228P	NULL
20230907001.3	OPA228PA	NULL
20230907001.3	OPA241PA	NULL
20230907001.3	OPA277P	NULL
20230907001.3	OPA277PA	NULL
20230907001.3	OPA27GP	NULL
20230907001.3	OPA4227PA	NULL
20230907001.3	TL034ACN	NULL
20230907001.3	TL054CN	NULL
20230907001.3	TL062CPSR	NULL
20230907001.3	TL071CPSR	NULL
20230907001.3	TL072MUB	NULL
20230907001.3	TL592B-8DR	NULL
20230907001.3	TLC271CP	NULL
20230907001.3	TLC27L2BCP	NULL
20230907001.3	TLC27M4CN	NULL
20230907001.3	TLC3702IP	NULL
20230907001.3	TLC372CP	NULL
20230907001.3	TLC372MFKB	NULL
20230907001.3	TLC393IP	NULL
20230907001.3	TLC556CN	NULL
20230907001.3	TLE2022AIP	NULL
20230907001.3	TLE2024QDWREP	NULL
20230907001.3	TLE2061AMJGB	NULL
20230907001.3	TLE2061MJGB	NULL
20230907001.3	TLE2064AMWB	NULL
20230907001.3	TLE2425CDR	NULL
20230907001.3	TLE2426CD	NULL

20230907001.3	TLE2426CLP	NULL
20230907001.3	TLE2426IDR	NULL
20230907001.3	TLV2264AMJB	NULL
20230907001.3	TLV2264IN	NULL
20230907001.3	TLV2461IP	NULL
20230907001.3	TLV2702IDGK	NULL
20230907001.3	TLV2771CDR	NULL
20230907001.3	TLV2772CP	NULL
20230907001.3	TLV3401IDR	NULL
20230907001.3	TLV3401IP	NULL
20230907001.3	TLV4111IDGN	NULL
20230908002.3	TLV1117LV28DCYR	NULL
20230908002.3	TLV1117LV30DCYR	NULL
20230908002.3	TLV117115DCYR	NULL
20230908002.3	TPS72501DCQR	NULL
20230908002.3	TPS72501DCQRG4	NULL
20230908002.3	TPS72515KTTR	NULL
20230908002.3	TPS72615KTTR	NULL
20230908002.3	TPS73216DBVT	NULL
20230908002.3	TPS73250QDCQRQ1	NULL
20230908002.3	TPS79425DCQR	NULL
20230918000.3	TPS61050DRCR	NULL
20230918000.3	TPS61050DRCT	NULL
20230918000.3	TPS65137ADSCR	NULL
20230920001.3	TL494IN	NULL
20230920001.3	TPS2811P	NULL
20230920001.3	TPS2812P	NULL
20230920001.3	TPS2814D	NULL
20230920001.3	TPS2814P	NULL
20230920001.3	TPS2814PW	NULL
20230920001.3	TPS2815D	NULL
20230920001.3	TPS2815P	NULL
20230920001.3	TPS2816DBVT	NULL
20230920001.3	TPS2817DBVT	NULL
20230920001.3	TPS2819DBVT	NULL
20230920001.3	TPS28225DRBT	NULL
20230920001.3	TPS2828DBVT	NULL
20230920001.3	TPS2830D	NULL
20230920001.3	TPS2830PWP	NULL
20230920001.3	TPS2834PWP	NULL
20230920001.3	TPS2835PWP	NULL
20230920001.3	UC2706DW	NULL
20230920001.3	UC2706N	NULL
20230920001.3	UC2709DW	NULL
20230920001.3	UC2852D	NULL
20230920001.3	UC2852N	NULL
20230920001.3	UC2853ADTR	NULL
20230920001.3	UC2854BN	NULL
20230920001.3	UC2854DW	NULL
20230920001.3	UC2854DWTR	NULL
20230920001.3	UC2854N	NULL
20230920001.3	UC2855ADW	NULL
20230920001.3	UC2855BDW	NULL
20230920001.3	UC2855BDWTR	NULL
20230920001.3	UC2855BN	NULL
20230920001.3	UC2856N	NULL
20230920001.3	UC2875N	NULL
20230920001.3	UC2879DWTR	NULL
20230920001.3	UC2879N	NULL

20230920001.3	UC2902N	NULL
20230920001.3	UC3715D	NULL
20230920001.3	UC3842ADW	NULL
20230920001.3	UC3845AJ	NULL
20230920001.3	UC3852D	NULL
20230920001.3	UC3852DTR	NULL
20230920001.3	UC3852N	NULL
20230920001.3	UC3853DTR	NULL
20230920001.3	UC3853N	NULL
20230920001.3	UC3854ADW	NULL
20230920001.3	UC3854ADWTR	NULL
20230920001.3	UC3854AN	NULL
20230920001.3	UC3854BN	NULL
20230920001.3	UC3854DWTR/80968	NULL
20230920001.3	UC3855ADW	NULL
20230920001.3	UC3855ADWTR	NULL
20230920001.3	UC3855BDW	NULL
20230920001.3	UC3855BDWTR	NULL
20230920001.3	UC3855BN	NULL
20230920001.3	UC3875N	NULL
20230920001.3	UC3879DW	NULL
20230920001.3	UC3879DWTR	NULL
20230920001.3	UC3879N	NULL
20230920001.3	UC3901N	NULL
20230920001.3	UC81522P	NULL
20230920001.3	UCC27210DRMT	NULL
20230920001.3	UCC27321P	NULL
20230920001.3	UCC27322P	NULL
20230920001.3	UCC27323P	NULL
20230920001.3	UCC27324P	NULL
20230920001.3	UCC27424P	NULL
20230920001.3	UCC27425P	NULL
20230920001.3	UCC28050D	NULL
20230920001.3	UCC28050DR	NULL
20230920001.3	UCC28050P	NULL
20230920001.3	UCC28051P	NULL
20230920001.3	UCC2817AD	NULL
20230920001.3	UCC2817ADR	NULL
20230920001.3	UCC2817D	NULL
20230920001.3	UCC2817DTR	NULL
20230920001.3	UCC2817DW	NULL
20230920001.3	UCC2817N	NULL
20230920001.3	UCC2818AD	NULL
20230920001.3	UCC2818AN	NULL
20230920001.3	UCC2818APW	NULL
20230920001.3	UCC2818DW	NULL
20230920001.3	UCC2818N	NULL
20230920001.3	UCC2819ADR	NULL
20230920001.3	UCC2819APW	NULL
20230920001.3	UCC2819APWR	NULL
20230920001.3	UCC28500DW	NULL
20230920001.3	UCC28500DWTR	NULL
20230920001.3	UCC28503DW	NULL
20230920001.3	UCC28634DR	NULL
20230920001.3	UCC2895N	NULL
20230920001.3	UCC2895PW	NULL
20230920001.3	UCC2961D	NULL
20230920001.3	UCC29950D	NULL
20230920001.3	UCC29950DR	NULL

20230920001.3	UCC37321P	NULL
20230920001.3	UCC37324P	NULL
20230920001.3	UCC38084PW	NULL
20230920001.3	UCC38084PWR	NULL
20230920001.3	UCC3817AD	NULL
20230920001.3	UCC3817D	NULL
20230920001.3	UCC3817DTR	NULL
20230920001.3	UCC3817DW	NULL
20230920001.3	UCC3817DWTR	NULL
20230920001.3	UCC3817N	NULL
20230920001.3	UCC3818AD	NULL
20230920001.3	UCC3818AN	NULL
20230920001.3	UCC3818APWR	NULL
20230920001.3	UCC3818D	NULL
20230920001.3	UCC3818N	NULL
20230920001.3	UCC3819AD	NULL
20230920001.3	UCC38500DW	NULL
20230920001.3	UCC38501DW	NULL
20230920001.3	UCC38502DW	NULL
20230920001.3	UCC38502DWTR	NULL
20230920001.3	UCC38503DWTR	NULL
20230920001.3	UCC3895DW	NULL
20230920001.3	UCC3895N	NULL
20230920001.3	UCC3895PW	NULL
20230922000.3	TAS5601DCA	NULL
20230922000.3	TAS5602DCA	NULL
20230922000.3	TAS5704PAP	NULL
20230922000.3	TAS5706APAPR	NULL
20230922000.3	TPA3120D2PWP	NULL
20230922000.3	TPA3120D2PWPR	NULL
20230922000.3	TPA6012A4PWPR	NULL
20230922000.3	TPA6021A4N	NULL
20230922000.3	TPA6043A4RHBR	NULL
20230925001.3	LM237KCSE3	NULL
20230925001.3	LM317LCLPR	NULL
20230925001.3	LM317LCPW	NULL
20230925001.3	LM317LCPWR	NULL
20230925001.3	LM317LILPR	NULL
20230925001.3	LP2950-30LP	NULL
20230925001.3	LP2950-30LPR	NULL
20230925001.3	LP2950-33LPE3	NULL
20230925001.3	LP2951-30D	NULL
20230925001.3	LP2951-30DR	NULL
20230925001.3	LP2951-30DRGR	NULL
20230925001.3	LP2951-50D	NULL
20230925001.3	LP2980AIM5X-2.5/NOPB	NULL
20230925001.3	LP2980AIM5X-4.7/NOPB	NULL
20230925001.3	LP2981A-33DBVRG4	NULL
20230925001.3	LP2981AIM5-3.6/NOPB	NULL
20230925001.3	LP2981IM5-3.6/NOPB	NULL
20230925001.3	LP2982AIM5X-3.3/NOPB	NULL
20230925001.3	LP2982IM5X-5.0/NOPB	NULL
20230925001.3	LP2983AIM5X-1.2/NOPB	NULL
20230925001.3	LP2985A-10DBVT	NULL
20230925001.3	LP2985A-28DBVR	NULL
20230925001.3	LP2985AIM5X-2.0/NOPB	NULL
20230925001.3	LP2985AIM5X-2.9/NOPB	NULL
20230925001.3	LP2989AIM-5.0/NOPB	NULL
20230925001.3	LP2989AIMM-5.0/NOPB	NULL

20230925001.3	LP2989IMX-5.0/NOPB	NULL
20230925001.3	LP2992AILD-5.0/NOPB	NULL
20230925001.3	LP2992AIM5X-2.5/NOPB	NULL
20230925001.3	LP2992ILD-2.5/NOPB	NULL
20230925001.3	LP2992ILD-5.0/NOPB	NULL
20230925001.3	LP2992ILD-1.5/NOPB	NULL
20230925001.3	LP2992ILD-3.3/NOPB	NULL
20230925001.3	LP2992ILD-5.0/NOPB	NULL
20230925001.3	LP2992IM5-2.5/NOPB	NULL
20230925001.3	LP2992IM5X-1.5/NOPB	NULL
20230925001.3	LP2992IM5X-2.5/NOPB	NULL
20230925001.3	MC79L05ACL	NULL
20230925001.3	MC79L05ACLPR	NULL
20230925001.3	MC79L12ACD	NULL
20230925001.3	MC79L12ACL	NULL
20230925001.3	MC79L12ACLPR	NULL
20230925001.3	MC79L15ACL	NULL
20230925001.3	REG1117A-1.8/2K5	NULL
20230925001.3	REG1117A-2.5/2K5	NULL
20230925001.3	SN1603833DBVR	NULL
20230925001.3	TL317CD	NULL
20230925001.3	TL317CLPR	NULL
20230925001.3	TLE4275QPWPRQ1	NULL
20230925001.3	TLV1117-18IDCY	NULL
20230925001.3	TLV1117-18IDRJR	NULL
20230925001.3	TLV1117-33CDRJR	NULL
20230925001.3	TLV1117-50IDRJR	NULL
20230925001.3	TLV1117CDRJR	NULL
20230925001.3	TLV1117IDRJR	NULL
20230925001.3	TLV1117IKCS	NULL
20230925001.3	TLV1117IKTTR	NULL
20230925001.3	TPS72301DDCR	NULL
20230925001.3	TPS7301QDR	NULL
20230925001.3	TPS7333QD	NULL
20230925001.3	TPS7333QDR	NULL
20230925001.3	TPS7350QDR	NULL
20230925001.3	TPS76130DBVR	NULL
20230925001.3	TPS76316DBVT	NULL
20230925001.3	TPS76318QDBVRQ1	NULL
20230925001.3	TPS76325DBVT	NULL
20230925001.3	TPS76325QDBVRG4Q1	NULL
20230925001.3	TPS76330DBVT	NULL
20230925001.3	TPS76338DBVR	NULL
20230925001.3	TPS76350QDBVRG4Q1	NULL
20230925001.3	TPS76650D	NULL
20230925001.3	TPS76901SHKJ	NULL
20230925001.3	TPS76901SHKQ	NULL
20230925001.3	TPS76933QDBVRG4Q1	NULL
20230925001.3	TPS77301DGKR	NULL
20230925001.3	TPS77333DGKR	NULL
20230925001.3	TPS77350DGKR	NULL
20230925001.3	TPS78833DBVT	NULL
20230925001.3	TPS7A4515DCQR	NULL
20230925001.3	UA723CDR	NULL
20230925001.3	UA723CN	NULL
20230925001.3	UA7808CKTTR	NULL
20230925001.3	UA7810CKCS	NULL
20230925001.3	UA7810CKTTR	NULL
20230925001.3	UA7812CKCS	NULL

20230925001.3	UA7815CKCS	NULL
20230925001.3	UA7824CKTTR	NULL
20230925001.3	UA78L05ACLPM	NULL
20230925001.3	UA78L05AID	NULL
20230925001.3	UA78L05AILP	NULL
20230925001.3	UA78L05AILPR	NULL
20230925001.3	UA78L05CD	NULL
20230925001.3	UA78L05CDR	NULL
20230925001.3	UA78L05CLPR	NULL
20230925001.3	UA78L06ACPK	NULL
20230925001.3	UA78L08ACDR	NULL
20230925001.3	UA78L08ACLPR	NULL
20230925001.3	UA78L09ACDR	NULL
20230925001.3	UA78L09ACLPR	NULL
20230925001.3	UA78L09ACLPE3	NULL
20230925001.3	UA78L10ACD	NULL
20230925001.3	UA78L10ACDR	NULL
20230925001.3	UA78L10ACLPR	NULL
20230925001.3	UA78L10ACLPR	NULL
20230925001.3	UA78L15ACLPR	NULL
20230925001.3	UA78M08CDCYR	NULL
20231004006.3	LM317KCS	NULL
20231004006.3	LM317LCD	NULL
20231004006.3	LM317LCDRG4	NULL
20231004006.3	LM317LCLP	NULL
20231004006.3	LM317LID	NULL
20231004006.3	LM317LILP	NULL
20231004006.3	LM317LIPWR	NULL
20231004006.3	LM337KCSE3	NULL
20231004006.3	LM337KTTR	NULL
20231004006.3	LP2951-33D	NULL
20231004006.3	LP2951D	NULL
20231004006.3	LP2985-10DBVR	NULL
20231004006.3	LP2985-10DBVT	NULL
20231004006.3	LP2985A-10DBVR	NULL
20231004006.3	LP2985A-18DBVJ	NULL
20231004006.3	LP2985AIM5-2.8/NOPB	NULL
20231004006.3	LP2985AIM5X-3.1/NOPB	NULL
20231004006.3	LP2985AIM5X-3.8/NOPB	NULL
20231004006.3	LP2989AILD-3.3/NOPB	NULL
20231004006.3	LP2989AILD-5.0/NOPB	NULL
20231004006.3	LP2989AIMX-3.3/NOPB	NULL
20231004006.3	LP2989ILD-3.3/NOPB	NULL
20231004006.3	LP2989ILD-5.0/NOPB	NULL
20231004006.3	LP2992AILD-3.3/NOPB	NULL
20231004006.3	LP2992AILD-5.0/NOPB	NULL
20231004006.3	LP2992AILD-3.3/NOPB	NULL
20231004006.3	LP2992ILD-1.8/NOPB	NULL
20231004006.3	LP2992ILD-3.3/NOPB	NULL
20231004006.3	MC79L05ACD	NULL
20231004006.3	MC79L05ACDR	NULL
20231004006.3	MC79L12ACDR	NULL
20231004006.3	REG1117	NULL
20231004006.3	REG1117-5	NULL
20231004006.3	REG1117/2K5	NULL
20231004006.3	REG1117A-2.5	NULL
20231004006.3	REG1117A/2K5	NULL
20231004006.3	TL317CPWR	NULL
20231004006.3	TL760M33QKVURQ1	NULL

20231004006.3	TL783CKCSE3	NULL
20231004006.3	TL783CKTTR	NULL
20231004006.3	TLV1117-33IDRJR	NULL
20231004006.3	TLV1117-50CDRJR	NULL
20231004006.3	TLV1117CDCY	NULL
20231004006.3	TLV1117IDCY	NULL
20231004006.3	TLV2217-33KCSE3	NULL
20231004006.3	TLV2217-33KVURG3	NULL
20231004006.3	TPS71519DCKR	NULL
20231004006.3	TPS71530QDCKRQ1	NULL
20231004006.3	TPS76201DBVR	NULL
20231004006.3	TPS76201DBVT	NULL
20231004006.3	TPS76201QDBVRQ1	NULL
20231004006.3	TPS76301QDBVRG4Q1	NULL
20231004006.3	TPS76316DBVR	NULL
20231004006.3	TPS76333QDBVRG4Q1	NULL
20231004006.3	TPS76601DR	NULL
20231004006.3	TPS76928DBVR	NULL
20231004006.3	TPS78833DBVR	NULL
20231004006.3	UA7805CKCS	NULL
20231004006.3	UA7805CKTTR	NULL
20231004006.3	UA7805CKTTRG3	NULL
20231004006.3	UA7812CKTTR	NULL
20231004006.3	UA78L05ACLCP	NULL
20231004006.3	UA78L05ACLPR	NULL
20231004006.3	UA78L05ACPKE6	NULL
20231004006.3	UA78L08ACPK	NULL
20231004006.3	UA78L09ACPK	NULL
20231004006.3	UA78L09ACPKE6	NULL
20231004006.3	UA78L10ACPK	NULL
20231004006.3	UA78L12ACD	NULL
20231004006.3	UA78L12ACLPR	NULL
20231004006.3	UA78M08CKVURG3	NULL
20231004006.3	UA7905CKCS	NULL
20231004006.3	UA7905CKTTR	NULL
20231004006.3	UA79M05CKVURG3	NULL
20231004006.3	UA79M08CKVURG3	NULL
20231005002.3	TPS71501MDCKREP	NULL
20231005002.3	TPS767D301MPWPREP	NULL
20231005002.3	TPS76801MPWPREP	NULL
20231005002.3	TPS76901SDBVTEP	NULL
20231005002.3	TPS7A4501MUB	NULL
20231018001.3	TPS2062ADRBR	NULL
20231018001.3	TPS2065QDGNRQ1	NULL
20231018002.3	SA5534ADR	NULL
20231018002.3	SA5534DR	NULL
20231018002.3	SA5534P	NULL
20231018002.3	THS4051IDGN	NULL
20231018002.3	THS6212YS	NULL
20231018002.3	TLV2302IP	NULL
20231018002.3	TSM102AIDR	NULL
20231018002.3	TSM102AIPWR	NULL
20231018002.3	TSM102IDR	NULL
20231018002.3	TSM102IPWR	NULL
20231018002.3	TSM104WIDR	NULL
20231018003.3	TPS79601KTTR	NULL
20231018003.3	TPS79633KTTR	NULL
20231019000.3	SN0809080DAPR	
20231019000.3	SN0809080DAPR	NULL

20231019000.3	SN1102050DR	
20231019000.3	SN1102050DR	NULL
20231019000.3	TPIC2810DRG4	NULL
20231019000.3	TPIC6259DWR	NULL
20231019000.3	TPIC6C595PW	NULL
20231019000.3	TPIC6C596DRG4	NULL
20231019000.3	TPIC6C596PW	NULL
20231019000.3	UCC2972PW	NULL
20231019001.3	UC1854BJ	NULL
20231019001.3	UC2907N	NULL
20231019001.3	UC3902N	NULL
20231019001.3	UC3907DWTR	NULL
20231019001.3	UC3907N	NULL
20231019001.3	UCC27210DDAR	NULL
20231019001.3	UCC27210DPRR	NULL
20231019001.3	UCC27210DRMR	NULL
20231019001.3	UCC29002P	NULL
20231024000.3	5962-87659022A	NULL
20231024000.3	5962-8765902CA	NULL
20231024000.3	5962-9096901M2A	NULL
20231024000.3	5962-9096901MCA	NULL
20231024000.3	5962-9688101QPA	NULL
20231024000.3	NE5534ADR	NULL
20231024000.3	NE5534AP	NULL
20231024000.3	NE5534DR	NULL
20231024000.3	NE5534P	NULL
20231024000.3	OPA170ASDRLTEP	NULL
20231024000.3	OPA2314ASDRBTEP	NULL
20231024000.3	TLC139MJB	NULL
20231024000.3	TLC193MJGB	NULL
20231024000.3	TLC3704MFKB	NULL
20231024000.3	TLV2354MFKB	NULL
20231024000.3	TSM102AIPW	NULL
20231029000.3	TPS5130QPTRQ1	NULL
20231029002.3	LM4121AIM5-ADJ/NOPB	NULL
20231029002.3	LM4121AIM5X-ADJ/NOPB	NULL
20231029002.3	LM4121IM5-ADJ/NOPB	NULL
20231029002.3	LM4121IM5X-ADJ/NOPB	NULL
20231031000.3	74AHCT1G126DBVRG4	NULL
20231031000.3	CAHCT1G126QDCKRG4Q	NULL
20231031000.3	CD4023BE-NG	NULL
20231031000.3	CD4093BE-NG	NULL
20231031000.3	CD74AC161M96	NULL
20231031000.3	CD74AC283M96	NULL
20231031000.3	CD74AC299M96	NULL
20231031000.3	CD74HC123E	NULL
20231031000.3	CD74HC14MT	NULL
20231031000.3	CD74HC423M96	NULL
20231031000.3	CD74HC74MT	NULL
20231031000.3	CD74HCT123M96	NULL
20231031000.3	CD74HCT221M96	NULL
20231031000.3	CD74HCT423M96	NULL
20231031000.3	SN74GTL2010PWR	NULL
20231031000.3	SN74HC244QDWRG4Q1	NULL
20231031000.3	SN74HC7032DT	NULL
20231031000.3	SN74LV123APWRG4	NULL
20231031000.3	SN74LV123ARGYR	NULL
20231031000.3	SN74LV123ATPWRG4Q1	NULL
20231031000.3	SN74LV221ADR	NULL



20231031000.3	SN74LV221APWR	NULL
20231031000.3	SN74LVU04AQPWRG4Q1	NULL
20231101001.3	MSA00010DBVR	
20231101001.3	MSA00010DBVR	
20231101001.3	MSA00011DBVR	
20231101001.3	MSA00011DBVR	
20231103000.3	BQ2000TPWR	NULL
20231103000.3	BQ2000TSN-B5	NULL
20231103000.3	BQ2000TSN-B5TR	NULL
20231103000.3	BQ2031PN-A5	NULL
20231103000.3	BQ2031SN-A5	NULL
20231103000.3	BQ2031SN-A5TR	NULL
20231103000.3	BQ2054SNTR	NULL
20231103000.3	BQ24020DRCR	NULL
20231103000.3	BQ24022DRCR	NULL
20231103000.3	BQ24023DRCR	NULL
20231103000.3	BQ24024DRCR	NULL
20231103000.3	BQ24025DRCR	NULL
20231103000.3	BQ24030RHLR	NULL
20231103000.3	BQ24038RHLR	NULL
20231103000.3	BQ24083DRCR	NULL
20231103000.3	BQ24083DRCT	NULL
20231103000.3	BQ24401PW	NULL
20231103000.3	BQ24401PWR	NULL
20231103000.3	BQ24765RUVR	NULL
20231103000.3	BQ24765RUVT	NULL
20231103000.3	BQ25015RHLR	NULL
20231114006.3	LP1763DR	NULL
20231114006.3	LP2981-28DBVTG4	NULL
20231114006.3	LP3878MR-ADJ/NOPB	NULL
20231114006.3	LP3878MRX-ADJ/NOPB	NULL
20231114006.3	LP3878SD-ADJ/NOPB	NULL
20231114006.3	LP3878SDX-ADJ/NOPB	NULL
20231114006.3	REG101NA-2.5/250	NULL
20231114006.3	REG101NA-2.8/250	NULL
20231114006.3	REG101NA-2.85/250	NULL
20231114006.3	REG101NA-2.85/3K	NULL
20231114006.3	REG101NA-3.3/250	NULL
20231114006.3	REG101NA-3.3/3K	NULL
20231114006.3	REG101NA-3/250	NULL
20231114006.3	REG101NA-5/250	NULL
20231114006.3	REG101NA-5/3K	NULL
20231114006.3	REG101NA-A/250	NULL
20231114006.3	REG101NA-A/3K	NULL
20231114006.3	REG101UA-2.5	NULL
20231114006.3	REG101UA-3.3	NULL
20231114006.3	REG101UA-5	NULL
20231114006.3	REG101UA-5/2K5	NULL
20231114006.3	REG101UA-A	NULL
20231114006.3	REG102GA-3.3	NULL
20231114006.3	REG102GA-3.3/2K5	NULL
20231114006.3	REG102GA-5	NULL
20231114006.3	REG102GA-A	NULL
20231114006.3	REG102GA-A/2K5	NULL
20231114006.3	REG102NA-3.3/250	NULL
20231114006.3	REG102NA-3.3/3K	NULL
20231114006.3	REG102NA-3/250	NULL
20231114006.3	REG102NA-3/3K	NULL
20231114006.3	REG102NA-5/250	NULL

20231114006.3	REG102NA-5/250G4	NULL
20231114006.3	REG102NA-5/3K	NULL
20231114006.3	REG102NA-A/250	NULL
20231114006.3	REG102NA-A/3K	NULL
20231114006.3	REG102UA-3.3	NULL
20231114006.3	REG102UA-5	NULL
20231114006.3	REG102UA-5/2K5	NULL
20231114006.3	REG103FA-3.3KTTT	NULL
20231114006.3	REG103FA-5KTTT	NULL
20231114006.3	REG103FA-AKTTT	NULL
20231114006.3	REG103GA-2.5	NULL
20231114006.3	REG103GA-3.3	NULL
20231114006.3	REG103GA-3.3/2K5	NULL
20231114006.3	REG103GA-5	NULL
20231114006.3	REG103GA-5/2K5	NULL
20231114006.3	REG103GA-A	NULL
20231114006.3	REG103GA-A/2K5	NULL
20231114006.3	REG103UA-2.5	NULL
20231114006.3	REG103UA-3.3	NULL
20231114006.3	REG103UA-3.3/2K5	NULL
20231114006.3	REG103UA-5	NULL
20231114006.3	REG103UA-5/2K5	NULL
20231114006.3	REG103UA-A	NULL
20231114006.3	REG103UA-A/2K5	NULL
20231114006.3	REG104FA-2.5KTTT	NULL
20231114006.3	REG104FA-3.3/500	NULL
20231114006.3	REG104FA-5/500	NULL
20231114006.3	REG104FA-A/500	NULL
20231114006.3	REG104GA-2.5	NULL
20231114006.3	REG104GA-3.3	NULL
20231114006.3	REG104GA-3.3/2K5	NULL
20231114006.3	REG104GA-5	NULL
20231114006.3	REG104GA-5/2K5	NULL
20231114006.3	REG104GA-5G4	NULL
20231114006.3	REG104GA-A	NULL
20231114006.3	REG104GA-A/2K5	NULL
20231114006.3	REG104GA-AG4	NULL
20231114006.3	REG113EA-3.3/250	NULL
20231114006.3	REG113EA-3.3/2K5	NULL
20231114006.3	REG113EA-5/250	NULL
20231114006.3	REG113EA-5/2K5	NULL
20231114006.3	REG113NA-2.5/250	NULL
20231114006.3	REG113NA-2.5/3K	NULL
20231114006.3	REG113NA-3.3/250	NULL
20231114006.3	REG113NA-3.3/3K	NULL
20231114006.3	REG113NA-3/250	NULL
20231114006.3	REG113NA-3/3K	NULL
20231114006.3	REG113NA-5/250	NULL
20231114006.3	REG113NA-5/3K	NULL
20231114006.3	TL317CDR	NULL
20231114006.3	TL5209DR	NULL
20231114006.3	TL720M05QPWPRQ1	NULL
20231114006.3	TL780-05KCS	NULL
20231114006.3	TL780-12KCS	NULL
20231114006.3	TL780-15KCS	NULL
20231114006.3	TPS76901QDBVRQ1	NULL
20231114006.3	TPS7H1201SHKS	NULL
20231114006.3	UA78M33CKCS	NULL
20231115000.3	ULN2002AN	NULL

20231115000.3	ULN2004AID	NULL
20231115000.3	ULN2004AIDR	NULL
20231115000.3	ULN2004AINSR	NULL
20231115000.3	ULN2004AN	NULL
20231115000.3	ULQ2003AN	NULL
20231115000.3	ULQ2004AD	NULL
20231115000.3	ULQ2004ADR	NULL
20231115000.3	ULQ2004AN	NULL
20231115000.3	ULQ2004ATDRQ1	NULL
20231126000.3	ADC0831CCWMX/NOPB	NULL
20231126000.3	ADC0832CCWM/NOPB	NULL
20231126000.3	ADC0832CCWMX/NOPB	NULL
20231126000.3	ADC0834CCWM/NOPB	NULL
20231126000.3	ADC0834CCWMX/NOPB	NULL
20231126000.3	ADC0838CCWM/NOPB	NULL
20231126000.3	ADC0838CCWMX/NOPB	NULL
20231126000.3	ADC0838CIWM/NOPB	NULL
20231126000.3	ADC0838CIWMX/NOPB	NULL
20231126000.3	ADS1201U	NULL
20231126000.3	ADS1201U/1K	NULL
20231126000.3	ADS1211U	NULL
20231126000.3	ADS1211U/1K	NULL
20231126000.3	ADS1213U	NULL
20231126000.3	ADS1213U/1K	NULL
20231126000.3	ADS774JU	NULL
20231126000.3	ADS774JU/1K	NULL
20231126000.3	ADS774KU	NULL
20231126000.3	ADS7800AH	NULL
20231126000.3	ADS7800BH	NULL
20231126000.3	ADS7800JU	NULL
20231126000.3	ADS7800JU/1K	NULL
20231126000.3	ADS7800KU	NULL
20231126000.3	ADS7804U	NULL
20231126000.3	ADS7804UB	NULL
20231126000.3	ADS7805U	NULL
20231126000.3	ADS7805U/1K	NULL
20231126000.3	ADS7805UB	NULL
20231126000.3	ADS7807U	NULL
20231126000.3	ADS7807UB	NULL
20231126000.3	ADS7808U	NULL
20231126000.3	ADS7808U/1K	NULL
20231126000.3	ADS7808UB	NULL
20231126000.3	ADS7809U	NULL
20231126000.3	ADS7809U/1K	NULL
20231126000.3	ADS7809UB	NULL
20231126000.3	ADS7809UB/1K	NULL
20231126000.3	ADS7811U	NULL
20231126000.3	ADS7811U-1/1K	NULL
20231126000.3	ADS7812PB	NULL
20231126000.3	ADS7812UB	NULL
20231126000.3	ADS7813U	NULL
20231126000.3	ADS7813UB	NULL
20231126000.3	ADS7815U	NULL
20231126000.3	ADS7824U	NULL
20231126000.3	ADS7824U/1K	NULL
20231126000.3	ADS7825U	NULL
20231126000.3	ADS7825UB	NULL
20231126000.3	ADS7825UB/1K	NULL
20231207004.3	TPS70302PWP	NULL

20231208002.3	SN103442DR	
20231213002.3	THS1206CDA	NULL
20231213002.3	THS1206CDAR	NULL
20231213002.3	THS1206IDA	NULL
20231213002.3	THS1206IDAR	NULL
20231213002.3	THS12082CDAR	NULL
20231213002.3	THS12082IDA	NULL
20231213002.3	TLC0838CDWR	NULL
20231213002.3	TLC0838CN	NULL
20231213002.3	TLC0838CPWR	NULL
20231213002.3	TLC0838IN	NULL
20231213002.3	TLC0838IPW	NULL
20231213002.3	TLC0838IPWR	NULL
20231213002.3	TLC1542CDW	NULL
20231213002.3	TLC1542CDWR	NULL
20231213002.3	TLC1542CN	NULL
20231213002.3	TLC1542IDW	NULL
20231213002.3	TLC1542IDWR	NULL
20231213002.3	TLC1542IN	NULL
20231213002.3	TLC1543CDB	NULL
20231213002.3	TLC1543CDBR	NULL
20231213002.3	TLC1543CDW	NULL
20231213002.3	TLC1543CDWR	NULL
20231213002.3	TLC1543CN	NULL
20231213002.3	TLC1543IDB	NULL
20231213002.3	TLC1543IDBR	NULL
20231213002.3	TLC1543IDW	NULL
20231213002.3	TLC1543IDWR	NULL
20231213002.3	TLC1543IN	NULL
20231213002.3	TLC2543CDB	NULL
20231213002.3	TLC2543CDBR	NULL
20231213002.3	TLC2543CDW	NULL
20231213002.3	TLC2543CDWR	NULL
20231213002.3	TLC2543CN	NULL
20231213002.3	TLC2543IDB	NULL
20231213002.3	TLC2543IDBR	NULL
20231213002.3	TLC2543IDW	NULL
20231213002.3	TLC2543IDWR	NULL
20231213002.3	TLC2543IN	NULL
20231213002.3	TLC2574IDW	NULL
20231213002.3	TLC2574IPW	NULL
20231213002.3	TLC2578IDW	NULL
20231213002.3	TLC2578IPW	NULL
20231213002.3	TLC3544CPW	NULL
20231213002.3	TLC3544IDW	NULL
20231213002.3	TLC3544IPW	NULL
20231213002.3	TLC3548CDW	NULL
20231213002.3	TLC3548CDWR	NULL
20231213002.3	TLC3548CPW	NULL
20231213002.3	TLC3548CPWR	NULL
20231213002.3	TLC3548IDW	NULL
20231213002.3	TLC3548IPW	NULL
20231213002.3	TLC3548IPWR	NULL
20231213002.3	TLC3574IDWR	NULL
20231213002.3	TLC3574IPW	NULL
20231213002.3	TLC3578IDW	NULL
20231213002.3	TLC3578IDWR	NULL
20231213002.3	TLC3578IPW	NULL
20231213002.3	TLC3578IPWR	NULL

20231213002.3	TLV0838CDW	NULL
20231213002.3	TLV0838CDWR	NULL
20231213002.3	TLV0838IDW	NULL
20231213002.3	TLV0838IDWR	NULL
20231213002.3	TLV0838IPW	NULL
20231213002.3	TLV0838IPWR	NULL
20231213002.3	TLV1504ID	NULL
20231213002.3	TLV1504IPW	NULL
20231213002.3	TLV1504IPWR	NULL
20231213002.3	TLV1508IDW	NULL
20231213002.3	TLV1508IPW	NULL
20231213002.3	TLV1508IPWR	NULL
20231213002.3	TLV1543CDB	NULL
20231213002.3	TLV1543CDBR	NULL
20231213002.3	TLV1543CDW	NULL
20231213002.3	TLV1543CDWR	NULL
20231213002.3	TLV1543IDB	NULL
20231213002.3	TLV1543IDBR	NULL
20231213002.3	TLV1544CDR	NULL
20231213002.3	TLV1544CPW	NULL
20231213002.3	TLV1544CPWR	NULL
20231213002.3	TLV1544ID	NULL
20231213002.3	TLV1544IDR	NULL
20231213002.3	TLV1544IPWR	NULL
20231213002.3	TLV1548CDBR	NULL
20231213002.3	TLV1548IDB	NULL
20231213002.3	TLV1548IDBR	NULL
20231213002.3	TLV1570CDW	NULL
20231213002.3	TLV1570IPW	NULL
20231213002.3	TLV1570IPWR	NULL
20231213002.3	TLV2543CDB	NULL
20231213002.3	TLV2543CDBR	NULL
20231213002.3	TLV2543IDB	NULL
20231213002.3	TLV2543IDBR	NULL
20231213002.3	TLV2543IDWR	NULL
20231213002.3	TLV2544CDR	NULL
20231213002.3	TLV2544CPWR	NULL
20231213002.3	TLV2544ID	NULL
20231213002.3	TLV2544IDR	NULL
20231213002.3	TLV2544IPW	NULL
20231213002.3	TLV2548CDW	NULL
20231213002.3	TLV2548CDWR	NULL
20231213002.3	TLV2548CPW	NULL
20231213002.3	TLV2548IDW	NULL
20231213002.3	TLV2548IDWR	NULL
20231213002.3	TLV2548IPW	NULL
20231213002.3	TLV2548IPWR	NULL
20231213002.3	TLV2553IDW	NULL
20231213002.3	TLV2553IDWR	NULL
20231213002.3	TLV2553IPW	NULL
20231213002.3	TLV2553IPWR	NULL
20231213002.3	TLV2556IDW	NULL
20231213002.3	TLV2556IDWR	NULL
20231213002.3	TLV2556IPW	NULL
20231213002.3	TLV2556IPWR	NULL
20231218001.3	TPL9201PWPR	NULL
20240110000.3	THS1206QDA	NULL
20240110004.3	AMC1203BDW	NULL
20240110004.3	AMC1203BDWR	NULL

20240110004.3	AMC1203DUB	NULL
20240110004.3	AMC1203PSA	NULL
20240110004.3	AMC1203PSAR	NULL
20240112000.3	CD74AC109M96	NULL
20240124001.3	TPIC6C596D	NULL
20240124001.3	TPIC6C596DG4	NULL
20240124001.3	TPIC6C596DR	NULL
20240124001.3	TPIC6C596DRDN	NULL
20240124001.3	TPIC6C596DRQ1	NULL
20240124001.3	TPIC6C596PWR	NULL
20240124001.3	TPIC6C596PWRG4	NULL
20240206000.3	LM337KVURG3	NULL
20240214002.3	DAC7725U	NULL
20240214002.3	DAC7725UB	NULL
20240214002.3	DAC7725UB/1K	NULL
20240214002.3	DAC811BH	NULL
20240220000.3	UCC2541PWPR	NULL

Details of this Product Notification follow on the next page(s).

<b>PDN Number:</b>	20240404000.3	<b>PDN Date:</b>	April 5, 2024
<b>Title:</b>	Addendum for discontinuance of select devices		
<b>Customer Contact:</b>	Change Management team	<b>Dept:</b>	Quality Services
<b>Change Type:</b>	Product Discontinuance - End Of Life		
<b>Product Notification Details</b>			
<b>Description of Addendum:</b>			
<p>Texas Instruments Incorporated (TI) is updating the status of select SFAB and DFAB devices which were previously planned for end-of-life (EOL). To best support production needs for the duration of customers' existing project lifecycles, applicable devices will remain orderable, and will no longer have a last-time buy date. You may continue to purchase these devices through your usual ordering process. The original PDN number(s) and corresponding part number(s) are listed starting on page 2 of this notice.</p>			
<b>Reason for Addendum:</b>			
<p>To best support production needs for the duration of customers' existing project lifecycles, the majority of devices manufactured in SFAB and DFAB will remain orderable, and will no longer have a last-time buy date.</p>			
<b>Product Affected:</b>			
<p>See list of devices starting on page 2 of this notice.</p>			

For questions regarding this notice, e-mails can be sent to the Change Management team or your local TI sales representative.

### **IMPORTANT NOTICE AND DISCLAIMER**

TI PROVIDES TECHNICAL AND RELIABILITY DATA (INCLUDING DATASHEETS), DESIGN RESOURCES (INCLUDING REFERENCE DESIGNS), APPLICATION OR OTHER DESIGN ADVICE, WEB TOOLS, SAFETY INFORMATION, AND OTHER RESOURCES "AS IS" AND WITH ALL FAULTS, AND DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING WITHOUT LIMITATION ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT OF THIRD PARTY INTELLECTUAL PROPERTY RIGHTS.

These resources are intended for skilled developers designing with TI products. You are solely responsible for (1) selecting the appropriate TI products for your application, (2) designing, validating and testing your application, and (3) ensuring your application meets applicable standards, and any other safety, security, or other requirements. These resources are subject to change without notice. TI grants you permission to use these resources only for development of an application that uses the TI products described in the resource. Other reproduction and display of these resources is prohibited. No license is granted to any other TI intellectual property right or to any third party intellectual property right. TI disclaims responsibility for, and you will fully indemnify TI and its representatives against, any claims, damages, costs, losses, and liabilities arising out of your use of these resources.

TI's products are provided subject to TI's Terms of Sale ([www.ti.com/legal/termsofsale.html](http://www.ti.com/legal/termsofsale.html)) or other applicable terms available either on [ti.com](http://ti.com) or provided in conjunction with such TI products. TI's provision of these resources does not expand or otherwise alter TI's applicable warranties or warranty disclaimers for TI products.