



Question 1.
This is soft-start circuit.
Is this external circuit correct?

Question 2.
 $T_{ss} = 3600 \times C_{ss}(\mu F)$
Is this formula correct?