



Stop activation with SS-PIN

thank you for your answer.

I have additional questions.

About the answer to Q1 and Q3

Look at the waveform on the left. During the first pulse, the SS pin voltage does not appear to fall below the VSENSE pin voltage.

Can you teach me specifically?

Malfunction due to noise etc. at the time of pulse output?

About answer of Q2,

-The delay time of the GDA driver is related to CSA and VAO. At what specific time does a delay occur?