bq24616EVM / Negative voltage on PH pin

[Background]

My customer confirmed PH pin voltage with default external component and no system load and battery, then the negative voltage over abs max rating though the duration was just about 300msec.

[Question]

Do you think this negative voltage will cause of damage?



