

Question:

Could you tell us how to modify code to use COM3 Slave?

- Autosen(AO001) react to COM2(38.4kbps) as you said.
- Our slave react to COM3(230.4kbps).

 But it seems not to be detected by IO_Link Master(TIDA-010016).

 (We cannot find "proper state change" message in teraterm console.)

port 0 state changed to 0
port 1 state changed to 0
port 2 state changed to 0
port 3 state changed to 0
port 4 state changed to 0
port 5 state changed to 0
port 6 state changed to 0
port 7 state changed to 0