




All Layers







Top Soldermask




Top Layer




Inner Layer 2 (GND)




Inner Layer 3 (PWR)




Bottom Soldermask



Bottom Layer



Drill



drp