

Question

Your TSC2013-Q1EVM is not equipped with resister and capacitor at X+, X-, Y+, Y- for noise filter of touch panel.

If we add noise filter, please tell me recommended values of resister and capacitor.