


# Timeout Error LA Analysis

1. During the last write operation, it was observed that cmd23 was set to write 168 sectors, but after cmd25 transferred only 8 sectors, the host side did not continue transmitting data.



2. On the LA waveform, it can be observed that after reading the logical address data 1DE849h via cmd18, the host side does not perform any operations for a long period of time.

