




changed procedures




[Procedure-1] JPG File Open




[Procedure-2] Image -> Mode -> Index




[Procedure-3] 16-color Select




[Procedure-4] Save as Export




[Procedure-5] *.pnm format Select




[Procedure-6] pnm Option Select



[Procedure-7] pnm image -> C format select



[Procedure-8] C File option Glib format Select



[Procedure-9] C File Conversion