



VOUT pad.

CIN, C1173 looks intact.

C1157 GND pad looks clean. Looks like the terminal from the cap was not soldered to the pad.

C1157 12V pad blown off.

12V vias.

Pin 1 pad here.

R829 intact.