



# Before applying Noise




# Half voltage output during applying noise①




Half voltage output during applying noise②

⇒ Vref was dropping 209.8mV



# After half output voltage during applying noise



# After stopping applying Noise

