



Measuring point





VOUT1_HSYNC (measured R636)



There is a blur in the falling timing.



24.2ns

